



HPE6-A79^{Q&As}

Aruba Certified Mobility Expert Written Exam

Pass HP HPE6-A79 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/hpe6-a79.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers



**QUESTION 1**

A network administrator has racked up a 7210 Mobility Controller (MC) that will be terminating 200+ Aps on a medium-size branch office. Next, the technician cabled the appliance with 4SPF+ Direct Attached Cables (DACs) distributed between two-member switching stack and powered it up.


What must the administrator do next in the MCs to assure maximum wired bandwidth utilization?

- A. Map the four physical ports to port channel 0.
- B. Disable spanning tree and allocate unique VLANs to each port.
- C. Manually set 10Gbps speeds on all ports.
- D. Configure the same MSTP region that the switches have.
- E. Make all ports trunk interfaces and permit data VLANs.

Correct Answer: C

QUESTION 2

Refer to the exhibits.





A user reports slow connectivity to a network administrator when connecting to AP-Garden and suggests that there might be a problem with the WLAN. The user's device supports 802.11n in the 2.4 GHz band. The network administrator finds the user in the Mobility Master (MM) and reviews the output shown in the exhibit.

What can the network administrator conclude after analyzing the data?

- A. 2.4GHz band is currently congested, therefore a NIC upgrade to 802.11ac or higher is recommended so the user can move to 5GHz.
- B. Channel usage is high and though this device has high speed the overall client rate is low on AP-Garden, there could be a few clients monopolizing the airtime on both bands at low speeds.
- C. User's SNR value over time is lower than recommended, therefore he should either get closer to the Access Point or increase the transmit power.
- D. 365s are low cost outdoor APs recommended for coverage design only. AP-Garden currently has more clients than recommended and is getting congested.

Correct Answer: D

QUESTION 3

Refer to the exhibit.

```
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_request.c:67] Add Request: id=45, server=ClearPass, IP=10.254.1.23, server-group=Employee, fd=63
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2367] Sending radius request to ClearPass:10.254.1.23:1812 id:45, len:260
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] User-Name: contractor12
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] NAS-IP-Address: 10.254.13.14
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] NAS-Port-Id: 0
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] NAS-Identifier: 10.254.13.14
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] NAS-Port-Type: Wireless-IEEE802.11
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] Calling-Station-Id: 608E9A910FT8
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] Called-Station-Id: 44646807DE4G
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] Service-Type: Framed User
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] Framed MTU: 1100
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] EAP-Message: \002\012
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] State: AGCATgBNAKj9IQQAkgYQjiu\avmnP5\OVna0FQ==
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] Aruba-Essid-Name: EmployeesNet
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] Aruba-Location-Id: AP22
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] Aruba-AP-Group: CAMPUS
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2381] Aruba-Device-Type: (VSA with invalid length - Don't send it)
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:2383] Message-Auth: \487e\326\445\540\318\F\789\416\110\874\4482\612
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:95] Find Request: id=45, server=(null), IP=10.254.1.23, server-group=(null) fd=63
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:104] Current entry: server=(null), IP=10.254.1.23, server-group=(null), fd=63
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:48] Del Request: id=45, server=ClearPass, IP=10.254.1.23, server-group=Employee, fd=63
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1228] Authentication Successful
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1230] RADIUS RESPONSE ATTRIBUTES:
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] {Aruba} Aruba-User-Role: contractor
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] {Microsoft} MS-MPPE-Recv-Key: \640\510\973>J\644\238n\421\789\252iP\612\439|K\0551\898h\354\519\733Fe0\450\739(\456\152="c\217bR\794\777\649\147\682\400\118\493y\452\731(\
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] {Microsoft} MS-MPPE-Send-Key: \641\486\489\011\605\784\064h\027\3824\677\723\884\375o\446\398\453
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] EAP-Message: \003\012
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] Message-Auth: z\498XS\330\480\512\383\498\711
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] User-Name: contractor12
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] Class: \202\005\456\123\789c\056\2578#\876\041\579"\656\741\081
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] PW_RADIUS_ID: -
Jun 23 21:28:17 :121031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] Rad-Length: 250
Jun 23 21:28:17 :124031: <5533> <DEBUG> |authmgr| |aaa| [rc_server.c:1245] PW_RAD_AUTHENTICATOR: PN\495\591\685\211\481\982G\363RD\261\696\025
Jun 23 21:28:17 :124003: <5533> <INFO> |authmgr| |aaa| [rc_server.c:1245] Authentication result= Authentication Successful(0), method=802.1x, server=ClearPass, user=xx:xx:xx:xx:xx:xx
```

A network administrator wants to allow contractors to access the WLAN named EmployeesNet. In order to restrict network access, the network administrator wants to assign this category of users to the contractor user role. To do this, the

network administrator configures ClearPass in a way that it returns the Aruba-User-Role with the contractor value.

When testing the solution, the network administrator receives the wrong role.

What should the network administrator do to assign the contractor role to contractor users without affecting any other



role assignment?

- A. Check the Download role from the CPPM option in the AAA profile.
- B. Set contractor as the default role in the AAA profile.
- C. Create Contractor firewall role in the M.
- D. Create server deviation rules in the server group.

Correct Answer: A

Reference: https://www.arubanetworks.com/techdocs/ClearPass/6.7/Aruba_DeployGd_HTML/Content/Aruba%20Controller%20Configuration/AAA_profile_adding.htm

QUESTION 4

A software development company has 764 employees who work from home. The company also has small offices located in different cities throughout the world. During working hours, they use RAPs to connect to a datacenter to upload software code as well as interact with databases.

In the past two month, cabling issues have occurred connection to the 7240XM Mobility Controller (MC) that runs ArubaOS 8 and terminates the RAPs. These RAPs disconnect, affecting the users connected to the RAPs. This also causes problems with code uploads and database synchronizations. Therefore, the company decides to add a second 7240XM controller for redundancy.

How should the network administrator deploy both controllers in order to provide the redundancy while preventing failover events from disconnecting users?

- A. Connect both controllers with common VLANs, and create an HA fast failover group with public addresses in the internet VLAN.
- B. Connect both controllers with common VLANs, and create an L2-connected cluster using public addresses in the internet VLAN.
- C. Connect both controllers with different VLANs, and create an L2-connected cluster using public addresses in the internet VLAN.
- D. Connect both controllers with common VLANs, and configure LMS/BLMS values equal to public addresses in the internet VLAN.

Correct Answer: A

QUESTION 5

Refer to the exhibit.



```
(MM1) [md] #show switches
```

```
All switches
```

IP Address g ID	IPv6 Address	Name	Location	Type	Mode	Version	Status	Configuration State	Config Sync Time (sec)	Confi
10.254.10.14	None	MM1	Building1.floor1	master	ArubaMM-VA	8.2.1.0_64044	up	UPDATE SUCCESSFUL	0	415
10.254.10.114	None	MM2	Building1.floor1	standby	ArubaMM-VA	8.2.1.0_64044	up	UPDATE SUCCESSFUL	0	415
10.1.140.100	None	MC1	Building1.floor1	MD	Aruba7030	8.2.1.0_64044	up	LINK(xx:xx:xx:xx:xx:xx)	N/A	N/A

```
Total Switches:3
```

```
(MM1) [md] #
```

A network administrator adds a Mobility Controller (MC) in the /mm level and notices that the device does not show up in the managed networks hierarchy. The network administrator accesses the CLI, executes the show switches command, and obtains the output shown in the exhibit.

What is the reason that the MC does not appear as a managed device in the hierarchy?

- A. The network administrator added the device using the wrong Pre-Shared Key (PSK).
- B. The network administrator has not moved the device into a group yet.
- C. The digital certificate of the MC is not trusted by the MM.
- D. The IP address of the MC does not match the one that was defined in the MM.

Correct Answer: D

[HPE6-A79 PDF Dumps](#)

[HPE6-A79 Study Guide](#)

[HPE6-A79 Exam Questions](#)