



# 76940X<sup>Q&As</sup>

Avaya Converged Platform Support

## Pass Avaya 76940X Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/76940x.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya  
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





### QUESTION 1

Before a switch that has failed can be replaced with a new switch, what needs to be done?

- A. The replacement switch needs to have its configs defaulted.
- B. The remaining switch that is not being replaced needs to have its configs reset to defaults.
- C. The switch can be replaced without any preparation.
- D. The switch needs to have the appropriate backup restored on it.

Correct Answer: A

---

### QUESTION 2

A support engineer is upgrading a PodFX 3.1 system to ACP 4200 4.0, and is upgrading the VMware vCenter Server from Release 6.0 to Release 6.5.

Which three tasks are required as part of the upgrade process? (Choose three.)

- A. Replace the old HP server with a new HP DL360 D10 server.
- B. Identify the IP address and root account credentials of the ESXi host where the current vCenter Server appliance resides.
- C. Obtain the VMware vCenter Server 6.5 license file.
- D. Obtain the VMware vCenter Server 6.5 upgrade file.
- E. Identify the IP address and root account credentials of the ESXi host where the new vCenter Server appliance will be deployed.

Correct Answer: BDE

Reference: <https://downloads.avaya.com/css/P8/documents/101061688>

---

### QUESTION 3

A support engineer is upgrading a PodFX 3.1 system to ACP 4200 4.0. In preparation for upgrading the HPE server firmware, the engineer notices that another colleague has already downloaded files.

Which two files should the engineer use? (Choose two.)

- A. hp-firmware-ilo4-2.60-1.1.i386.rpm
- B. bp-avaya-dl360g9-g10-ACP-4\_0-New-only.iso
- C. SP99382.exe
- D. ACP\_40\_ilo4\_261.bin




Correct Answer: BD

Reference: [https://support.avaya.com/downloads/download-details.action?contentId=C201811141048316790\\_5andproductId=P1704](https://support.avaya.com/downloads/download-details.action?contentId=C201811141048316790_5andproductId=P1704)

#### QUESTION 4

Rack view AL\_ACP\_AL\_ACP\_RACK



Refer to the exhibit.

When a support engineer navigates to Orchestrator's Rack View of an ACP 4200 system, the engineer



notices that the V1-V6 slots on the right of the diagram are not populated.

What could be causing this problem?

- A. V1-V6 are used to represent Virtual Machines which are not present in this particular system.
- B. V1-V6 are used to represent Vertical PDUs which are not present in this particular system.
- C. V1-V6 are used to represent G450 Media Modules which are not present in this particular system.
- D. V1-V6 are only used for ACP 100 systems.

Correct Answer: A

---

#### QUESTION 5

Which equipment is standard in a new ACP 4200 4.0?

- A. IP 7254
- B. VSP 4850
- C. IP 8284
- D. VSP 7024

Correct Answer: B

Reference: <https://downloads.avaya.com/css/P8/documents/101054952>

[76940X PDF Dumps](#)

[76940X Practice Test](#)

[76940X Exam Questions](#)