



# E20-340<sup>Q&As</sup>

Clariion solutionsgs implementation

## Pass EMC E20-340 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/e20-340.html>

100% Passing Guarantee  
100% Money Back Assurance


Following Questions and Answers are all new published by EMC  
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers



**QUESTION 1**

Refer to the exhibit.



What is the correct order of the management module components?

- A. A-GbE Service LAN; B-GbE Management LAN; C-Service Port COM1; D-SPS Port COM2; E- NMI Button
- B. A-GbE Management LAN; B-GbE Service LAN; C-Service Port COM1; D-SPS Port COM2; E- NMI Button
- C. A-SPS Port COM2; B-NMI Button; C-Service Port COM1; D-GbE Service LAN; E-GbE Management LAN
- D. A-GbE Service LAN; B-GbE Management LAN; C-SPS Port COM2; D-Service Port COM1; E- NMI Button

Correct Answer: A

---

**QUESTION 2**

You have set up and are using ALUA and PowerPath with your CLARiiON CX4-480 array. You have just experienced a front-end path failure.

Which driver will route the I/O to the SP owning the LUNs through the CMI channel?

- A. Upper redirector
- B. CLARiiON Management Interface
- C. ArrayCommPath
- D. Channel redirector



Correct Answer: A

---

### QUESTION 3

A customer has requested onsite assistance because they are currently unable to communicate with SPA. You arrive onsite and connect to the GbE Service LAN. What IP address do you use to connect to SPA?

- A. 128.221.1.250
- B. 192.168.1.250
- C. 128.221.1.251
- D. 192.168.1.251

Correct Answer: A

---

### QUESTION 4

A customer is using MV/A in a remote data center to protect a LUN. They also use the same source LUN for an ISC job to distribute the content of their parts catalogue to 27 regional offices.

What is the maximum number of snapshots of the source LUN they can take if they need to use a SnapView Recovery Session?

- A. 5
- B. 8
- C. 7
- D. 6

Correct Answer: A

---

### QUESTION 5

A customer is unable to connect to a CX4 after assigning an IP address to their iSCSI HBA. What needs to be configured in order to make a connection?

- A. Initiator network parameters
- B. iSCSI security
- C. iSCSI.conf file
- D. Initiator registration

Correct Answer: A

---



VCE & PDF

PassApply.com

<https://www.passapply.com/e20-340.html>

2024 Latest passapply E20-340 PDF and VCE dumps Download

---

[E20-340 VCE Dumps](#)

[E20-340 Study Guide](#)

[E20-340 Braindumps](#)