



E20-616^{Q&As}

Symmetrix Installation and Troubleshooting Specialist

Pass EMC E20-616 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/e20-616.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

Which SRDF/A feature offloads from cache to a dedicated device pool?

- A. Delta Set Extension
- B. Write Pacing
- C. Transmit Idle
- D. SRDF Compression

Correct Answer: A

QUESTION 2

You are reviewing a VMAX configuration and find 4 Diskless devices. Which type of Symmetrix VMAX feature is configured?

- A. Cascaded
- B. Auto-Provsioning
- C. Virtual-Provisioning
- D. SNAP

Correct Answer: A

QUESTION 3

A SIB replacement is required on VMAX. The customer asks what the impact will be on the front-end ports. What should your response be?

- A. VMAX 40K all front-end ports will remain online. VMAX 20K, VMAX 10K front-end ports will go offline
- B. VMAX 40K, VMAX 20K all front-end ports will remain online. VMAX 10K front-end ports will go offline
- C. VMAX 40K, VMAX 20K and VMAX 10K all front-end ports will remain online
- D. VMAX 40K, VMAX 20K and VMAX 10K front-end ports will go offline

Correct Answer: A

QUESTION 4

What is the maximum distance for System Bay Dispersion in a VMAX 40K configuration?

- A. 82.0 feet/25m



- B. 32.8 feet/10m
- C. 16.4 feet/5m
- D. 49.2 feet/15m

Correct Answer: A

QUESTION 5

You are preparing to run a health check on a VMAX 10K and log into the Service Processor, but cannot locate the icon for Simplified SymmWin on the desktop.

What is the most likely reason Simplified SymmWin is not available?

- A. The VMAX is running Enginuity version 5875
- B. Simplified SymmWin is not supported on VMAX 10K
- C. Engineering credentials are required for Simplified SymmWin
- D. Service Processor code upgrade has not been committed

Correct Answer: A

[Latest E20-616 Dumps](#)

[E20-616 PDF Dumps](#)

[E20-616 Practice Test](#)