



HP2-T23^{Q&As}

Supporting Industry Standard Server Solutions

Pass HP HP2-T23 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/hp2-t23.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

What is a result of selecting the Allow Non-Bundled Versions in HP SUM?

- A. Other non-bundled products can be added to the bundle.
- B. All available firmware will be overwritten.
- C. All products will be updated, including other manufacturers' firmware, and updates will be installed with the bundle.
- D. Old and new firmware files can be added and be installed with the bundle.

Correct Answer: D

QUESTION 2

An engineer repaired a memory problem in a ProLiant BL460c Gen8 server blade running Windows 2008 R2. What should the engineer do to verify the repair? (Select two.)

- A. Observe the Insight Display at the front of the server after it boots.
- B. Check the Active Health System.
- C. Observe the server console for POST errors.
- D. Reboot the BL460c Gen8 server and run the offline Insight Diagnostics.
- E. Reseat the memory and inform the customer when the job is done.

Correct Answer: AD

QUESTION 3

An HP VC Flex-10 module must be replaced in a c3000 BladeSystem enclosure because one uplink port is defective.

What must you do before physically replacing the module?

- A. Copy the VCM logs to a flash drive.
- B. Copy the server profiles to a flash drive.
- C. Back up the Virtual Connect settings.
- D. Back up the enclosure EBIPA information.

Correct Answer: C

QUESTION 4



Which Customer Service Repair (CSR) category allows a customer to have HP replace a failed part under warranty at no additional charge?

- A. CSR Advance Unit Replacement
- B. CSR mandatory
- C. CSR express
- D. CSR optional

Correct Answer: D

QUESTION 5

An engineer added a second Onboard Administrator (OA) module to a c7000 enclosure so the OAs are redundant. The modules, however, are not at the same firmware level. What is an easy way to bring them to the same firmware version?

- A. Use HP SUM to update both OAs simultaneously
- B. Use the Synchronize Firmware feature in either OA
- C. Use HP SUM Offline to update the standby OA, restart it, and repeat the procedure on the remaining OA.
- D. Use HP Systems Insight Manager (HP SIM) to push the updates to each OA.

Correct Answer: C

[HP2-T23 PDF Dumps](#)

[HP2-T23 Study Guide](#)

[HP2-T23 Braindumps](#)