



ACMP_6.3^{Q&As}

Aruba Certified Mobility Professional 6.3

Pass Aruba ACMP_6.3 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/acmp-6-3.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Aruba
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

Which of the following could be used to set a user's post-authentication role or VLAN association? (Choose two)

- A. AAA default role for authentication method
- B. Server Derivation Rule
- C. Vendor Specific Attributes
- D. AP Derivation Rule
- E. The Global AAA profile

Correct Answer: BC

QUESTION 2

How does the ARM Band Steering feature encourage 5GHz capable clients to move/connect to the 5GHz radios of Aruba APs?

- A. ARM suppresses the probe response on the 2.4 GHz radio
- B. ARM utilizes third party software on the wireless clients
- C. Current Wi-Fi chipset firmware supports this by default
- D. It's not possible to move clients to 5GHz radios when they can see both 2.4 and 5GHz APs
- E. ARM disables the 2.4GHz radio for the specified client

Correct Answer: A

QUESTION 3

With Fast-Failover disabled, to which IP address should the Aruba AP terminate its GRE tunnel for layer 2 controller redundancy to work and to support failover of access points?

- A. VRRP IP address
- B. management IP of an Aruba controller
- C. management IP of the backup Aruba controller
- D. HSRP IP address
- E. Loopback IP address of backup Aruba controller

Correct Answer: A

**QUESTION 4**

An Aruba controller is configured with the correct IP address and gateway information and is connected to the corporate LAN via a core layer 2 switch. Control Plane Security is not enabled on the network. An access point is provisioned with AP name and group and connected to a different Layer 2 switch on the corporate LAN that has IP connectivity to the core layer 2 switch. The AP powers on and layer 2 connects to the network, but the wireless radios do not power on.

Which could cause this condition? (Choose two)

- A. the layer 2 switches have ACLs that block GRE traffic
- B. the layer 2 switches are configured to block IPSec traffic
- C. a DHCP server is not configured for the segment to which the AP is connected
- D. the AP's mac address needs to be configured in the Aruba controller whitelist.
- E. the AP and controller are in different subnets

Correct Answer: AC

QUESTION 5

Exhibit: Referring to the above screen capture, if an administrator desires to change a specific AP into a Spectrum Monitor without assigning the AP to a new group, which menus could be used?



WIZARDS

AP

Controller

Campus WLAN

Remote AP

WIP

AirWave

NETWORK

> **Controller**

VLANs

Ports

Uplink

IP

SECURITY

Authentication

Access Control

WIRELESS

AP Configuration

AP Installation

MANAGEMENT

General

Administration

Certificates

SNMP

Logging

Clock

Guest Provisioning

Captive Portal

SMTP

Bandwidth Calculator

Threshold

ADVANCED SERVICES

Redundancy

IP Mobility

Stateful Firewall

External Services

VPN Services

Wired Access

All Profiles

A. Network > Controller

B. Wireless > AP Configuration



C. Wireless > AP Installation

D. Advanced Services > Wireless

E. Wizards > WIP Wizard

Correct Answer: B

[ACMP_6.3 PDF Dumps](#)

[ACMP_6.3 Exam Questions](#)

[ACMP_6.3 Braindumps](#)