300-180^{Q&As}

300-180$^{Q\&As}$

Troubleshooting Cisco Data Center Infrastructure

Pass Cisco 300-180 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/300-180.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

From Cisco UCS Central, you plan to add two Cisco UCS domains that use the same name for the WWPN pool. What must you do to ensure a successful Integration?

A. Rename the pools to have the same name.

B. Assign WWPN pools to Different users.

C. Move the WWPN pools to different organizations.

D. Remove duplicate WWPN pools.

Correct Answer: D

QUESTION 2

Refer to the exhibit. The VEMs fail to join a Cisco Nexus 1000V Series Switch. You determine that a system VLAN must be set on a system-uplink port profile. Which VLAN do you configure as a system VLAN?

A. 40

B. 10

C. 20

D. 30

Correct Answer: B

QUESTION 3

Where do you configure users so that they cannot access resources that belong to other organizations?

A. roles

B. domain separation

C. locals

D. VDCs

Correct Answer: C

QUESTION 4

When you look at the HSRP state for devices on a VLAN that is extended by OTV, you see the following states: Active, Standby, and Listen. However, you intended each data center device to show the state as Active and Standby. What is the problem?

A. HSRP is not configured correctly.

B. A VACL is missing.

C. A PACL is missing.

D. This cannot be done.

Correct Answer: B

QUESTION 5

Refer to exhibit.

```
aci-sol-calo-ucsb-A(nxos)# show interface vethernet 813
Vethernet813 is down (initializing)
    Bound Interface is port-channel1282
    Port description is server 1/1, VNIC Data-A
    Hardware is Virtual, address is 8c60.4f01.4420
    Port mode is trunk
    Speed is auto-speed
    Duplex mode is auto
  300 seconds input rate 0 bits/sec, 0 packets/sec
  300 seconds output rate 0 bits/sec, 0 packets/sec
  Rx
    0 unicast packets  0 multicast packets  115 broadcast packets
    115 input packets  32934 bytes
    0 input packet drops
  Tx
    0 unicast packets  29 multicast packets  0 broadcast packets
29 output packets  8729 bytes
0 flood packets
    0 output packet drops
```

A Cisco UCS admin is troubleshooting an issue with a vNIC not coming up on a blade. When looking at the CLI of the "Fabric Interconnect",the admin runs this command to view the status of the interface. Which option describes a possible reason why the interface is stuck in an "initializing" state?

A. The service profile is not applied to a blade.

B. The VLANs defined on the vNIC are not defined on a matching uplink port.

C. The uplink port is down.

D. The QoS policy on the vNIC is invalid.

E. The MTU on the vNIC is higher than the MTU configured in the QoS system class.

Correct Answer: C

Latest 300-180 Dumps   300-180 Practice Test   300-180 Exam Questions

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product !

100% Guaranteed Success
100% Money Back Guarantee
365 Days Free Update
Instant Download After Purchase
24x7 Customer Support
Average 99.9% Success Rate
More than 800,000 Satisfied Customers Worldwide
Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications.
You can view Vendor list of All Certification Exams offered:

https://www.passapply.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you.
To update a previously submitted ticket: