300-370^{Q&As}

Troubleshooting Cisco Wireless Enterprise Networks

Pass Cisco 300-370 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/300-370.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

A mobile workstation in a factory contains an AP that is configured as a workgroup bridge. When the workstation moves, it loses connectivity and disrupts operation. What can the engineer implement to minimize roaming problems?

A. Use 802.1X authentication.

B. Use Cisco Centralized Key Management for fast roaming.

C. Use AES for encryption.

D. Use the mobile station command.

Correct Answer: B

QUESTION 2

Which modulation, which was introduced in 802.11ac standard, influences end-user experience by providing the highest data rates and throughput?

A. 256 QAM

B. QPSK

C. 16 QAM

D. 64 QAM

Correct Answer: A

QUESTION 3

Refer to the exhibit.

```
Thu Aug 1   16:23:27   2013   AP   with MAC bb:1f:11:1f:1d:3f (APbb1f.111f.1d3f) is      unknown.
Thu Aug 1   16:23:27   2013   AP   Associated. Base Radio MAC: bb:1f:11:1f:1d:3f
Thu Aug 1   16:23:13   2013   AP   Disassociated: Base Radio MAC:bb:1f:11:1f:1d:3f
Thu Aug 1   16:23:16   2013   AP   with MAC bb:1f:11:1f:1d:3f (APbb1f.111f.1d3f) is      unknown.
Thu Aug 1   16:23:16   2013   AP   Associated. Base Radio MAC: bb:1f:11:1f:1d:3f
Thu Aug 1   16:23:08   2013   AP   Disassociated. Base Radio MAC:bb:1f:11:1f:1d:3f
Thu Aug 1   16:23:04   2013   AP   with MAC bb:1f:11:1f:1d:3f (APbb1f.111f.1d3f) is      unknown.
```

The AP is unable to join the controller. What is the cause of this error?

A. The controller code version is lower than the code of the AP attempting to join.

B. AP code is not the same as the controller and must download firmware.

C. AP model is not compatible with the controller code version.

D. The AP is not configured in the controller auth-list of acceptable APs.

Correct Answer: C

QUESTION 4

Refer to the exhibit.

An engineer is troubleshooting non-802.11 interference and observes the shown output. Which interference signature is depicted?

A. cordless phone

B. analog video cameras

C. microwave oven

D. FHSS Bluetooth

Correct Answer: B

QUESTION 5

A wireless user is experiencing connectivity issues with their Mac OS laptop. If the Mac is exhibiting the behavior of a "sticky client," how can the tech verify which AP the user is currently connected to?

A. Hold shift while clicking the wireless icon.

B. Hold option while clicking the wireless icon.

C. Hold control while clicking the wireless icon.

D. Hold command while clicking the wireless icon.

Correct Answer: B

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product !

100% Guaranteed Success
100% Money Back Guarantee
365 Days Free Update
Instant Download After Purchase
24x7 Customer Support
Average 99.9% Success Rate
More than 800,000 Satisfied Customers Worldwide
Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.passapply.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you.
To update a previously submitted ticket: