7004.1^{Q&As}

Avaya Communication Server 1000 for Avaya Aura® Maintenance Exam

Pass Avaya 7004.1 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/7004-1.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Avaya Official Exam Center

🔧 **Instant Download** After Purchase

🔧 **100% Money Back** Guarantee

🔧 **365 Days** Free Update

🔧 **800,000+** Satisfied Customers

QUESTION 1

Click the Exhibit button.

Given the customer\'s programmed database shown in the exhibit and AC 1 = 9, over which RLI will a call placed to 9-1-912-534-2222 complete?

A. RLI 9

B. RLI 4

C. RLI 3

D. RLI 2

E. call will not complete as dialed

Correct Answer: B

QUESTION 2

Click the Exhibit button.

A Communication Server 1000 RIs. 7 x customer is adding a new Human Resource department with eight IP telephone users. The customer has asked for the telephones to be programmed with consecutive Directory Number (DNs) from their DID range (2000-2099). Which number sequence is available to meet the customer\'s requirements?

A. 2001 2008

B. 2010 2017

C. 2050 2057

D. 2091 - 2098

Correct Answer: D

QUESTION 3

A customer would like to simplify their network administration by migrating existing Communication Server (CS) 1000 RIs. 7 x system in multiple locations into a single centrally deployed CS 1000 system. They want this change to be transparent to the end users so that can continue to use the same dial plan and features currently in place. Which feature can you implement to meet the customer\'s requirements?

A. Hybrid Dialing

B. Uniform Dialing

C. Zone Based Dialing

D. Coordinated Dialing

Correct Answer: B

QUESTION 4

Click the Exhibit button.

Refer to the customer\'s dialing plan and programming show in the exhibits. Assuming all required Route List Indexes have been programmed, why will the station user\'s dialed call of 8-1-717-398-8001 not complete?

A. AC2 Access Code was not dialed

B. NPA1717isnot provisioned in the customer\'s database

C. 398-8001 would be denied under the SDRR programming

D. AC1 AccessCodewas not dialed

Correct Answer: C

QUESTION 5

A customer has just deployed a new Communication Server 1000 RIs. 7 x High Availability system. You

have been instructed to configure the required virtual routes to comply with the company\\'s dialing plan

strategy.

Which Feature Package must be enabled to allow virtual routes on the system?

A. Package 147 ISDN Signaling Link

B. Package 148 Advanced ISDN Network Services

C. Package 145 integrated Services Digital Network

D. Package 161 ISDN Supplementary Features

Correct Answer: B

7004.1 PDF Dumps   7004.1 Exam Questions   7004.1 Braindumps