C_TPLM40_65^{Q&As}

SAP Certified Application Associate - Quality Management with SAP ERP 6.0 EHP5

Pass SAP C_TPLM40_65 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/c_tplm40_65.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by SAP Official Exam Center

QUESTION 1

Which statements are correct? (More than one answer is true.)

A. You use control charts to control or monitor one or more processes. In the task list characteristics, you use the SPC criterion to define these processes are to be combined or separated from one another (which inspection lots refer to a common control chart).

B. The SPC criterion controls how processes are combined or separated for a control chart (that is which inspection lots refer to a common control chart).

C. You make the preparations for a control chart in the sampling procedure and the task list or master inspection characteristic.

D. You cannot use the control chart to valuate inspection results. If an appropriate valuation rule is used, a sample can be rejected if at least one of the action limits in the related control chart is exceeded.

Correct Answer: ABC

QUESTION 2

The Software Deployment Manager (SDM) runs in its own Java Virtual Machine.

A. Correct

B. Incorrect

Correct Answer: A

QUESTION 3

An InfoSet can be assigned to several user types.

A. Incorrect

B. Correct

Correct Answer: A

QUESTION 4

Which are different processing options in the worklist?

A. Details for task list header

B. General settings for task list headers

C. QM-relevant settings for task list headers

D. Administrative data for task list headers

Correct Answer: A

QUESTION 5

QM is integrated in the processes of the logistics supply chain.

A. Correct

B. Incorrect

Correct Answer: A

C_TPLM40_65 PDF Dumps   C_TPLM40_65 Practice   C_TPLM40_65 Braindumps
                                         Test