**VCE & PDF**
**PassApply.com**

# E20-616^Q&As

## Symmetrix Installation and Troubleshooting Specialist

## Pass EMC E20-616 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

**https://www.passapply.com/e20-616.html**

### 100% Passing Guarantee
### 100% Money Back Assurance

Following Questions and Answers are all new published by EMC
Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

**QUESTION 1**

You are preparing to run a health check on a VMAX 10K and log into the Service Processor, but cannot locate the icon for Simplified SymmWin on the desktop.

What is the most likely reason Simplified SymmWin is not available?

A. The VMAX is running Enginuity version 5875

B. Simplified SymmWin is not supported on VMAX 10K

C. Engineering credentials are required for Simplified SymmWin

D. Service Processor code upgrade has not been committed

Correct Answer: A

**QUESTION 2**

What is the vault hyper size in GB for configuring a new VMAX 40K?

A. 9

B. 5

C. 4.5

D. 0.5

Correct Answer: A

**QUESTION 3**

Refer to the exhibit.

When would you use the \\'EAN\\' bit setting in SymmWin?

A. If the SAN speed is unknown

B. To enable SAN topology

C. To Enable iSCSI negotiation

D. If IP network speed will be negotiated

Correct Answer: A

---

**QUESTION 4**

Which action needs to be taken if the Backend Cabling Verification fails after a Data Center relocation?

A. Contact PSE Lab for assistance.

B. Relocate the cables shown as faulted.

C. Replace the cables shown as faulted.

D. Power down and re-start the Backend Cabling Verification script.

Correct Answer: A

---

**QUESTION 5**

Refer to the exhibit.



For what is the ELM tool used?

A. Manage Symmetrix Licenses

B. Environmental LCC Management

C. ELM scheduler task

D. Create Environmental scripts

Correct Answer: A