HPE6-A29 Q&As

Aruba Certified Mobility Professional 6.4

Pass HP HPE6-A29 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/hpe6-a29.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- **Instant Download** After Purchase
- **100% Money Back** Guarantee
- **365 Days** Free Update
- **800,000+** Satisfied Customers

QUESTION 1

One hundred (100) additional APs were deployed in an existing network. But some APs are not able to connect to the lms-ip address, even though all of the APs belong to the same AP group. Which of the following are NOT potential causes? (Choose two).

A. The problem APs are not getting an IP address.

B. The problem APs have the wrong lms-ip address setting.

C. There is a firewall between the problem APs and the controller blocking PAPI.

D. The controller does not support that many APs in a single AP-Group.

E. There are not enough AP licenses to support the additional quantity of APs.

Correct Answer: BD

QUESTION 2

An administrator wants Aps to boot and discover the master controller in a master-local topology. After connect to the master, the Aps will connect to the appropriate local controller based on the AP Group configuration. DNS will be used to discover the master controller\\'s IP address?

A. aruba-discovery company.com

B. master.company.com

C. activate.arubanetworks.com

D. aruba-master.company.com

Correct Answer: D

QUESTION 3

Which of the following APs support remote AP operation?

A. AP 105

B. AP 125

C. RAP2

D. All of the above

Correct Answer: D

QUESTION 4

Which of the following statements is true?

A. Aruba Campus APs must be physically attached to the Aruba Controller.

B. Aruba Campus APs must be in the same broadcast domain as the Controller.

C. Aruba Campus APs can be in different subnets from the Controller.

D. Aruba Campus APs must be physically attached to the same Layer 3 switch.

E. Aruba Campus APs can be connected directly to the public internet.

Correct Answer: C

QUESTION 5



Referring to the diagram provided for this question, an employee brought an unauthorized AP from home and attached the LAN port to the cubicle Ethernet port. All Aruba APs and AMs as well as the employee AP are in VLAN 80 and within RF range of each other. No traffic from the wired or wireless network has passed through the unauthorized AP yet, but the AP began wireless broadcasts.

How will the Aruba system initially classify the employee\\'s non-Aruba AP?

A. a valid AP

B. an AM

C. a Rogue AP

D. an interfering AP

E. a known interfering AP

Correct Answer: D

Latest HPE6-A29 Dumps HPE6-A29 VCE Dumps HPE6-A29 Exam Questions