NS0-509^{Q&As}

NetApp Certified Implementation Engineer - SAN - ONTAP

Pass NetApp NS0-509 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/ns0-509.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by NetApp
Official Exam Center

⚙ **Instant Download** After Purchase

⚙ **100% Money Back** Guarantee

⚙ **365 Days** Free Update

⚙ **800,000+** Satisfied Customers

QUESTION 1

You want to ensure maximum performance of iSCSI LUNs on an AFF A220. In this scenario, which two actions will accomplish this task? (Choose two.)

A. Disable flow control.

B. Configure virtual LAN (VLAN).

C. Enable flow control.

D. Enable jumbo frames.

Correct Answer: CD

QUESTION 2

Which path selection policy is used by Windows Servers using NetApp LUNs that are greater than 2 TB?

A. Least Queue Depth

B. Round Robin

C. Round Robin with Subset Policy

D. Least Weighted Paths

Correct Answer: C

Reference:
https://library.netapp.com/ecmdocs/ECMP1307349/html/GUID-29CBF302-D78C-4A38-900D9F1E8DDB0D6A.html

QUESTION 3

You have three Windows servers and one Linux server, each with dual-ported HBAs that are connected into a dual fabric.

In this scenario, what is the minimum number of zones that you need to create within each fabric switch?

B. 1

C. 4

D. 2

Correct Answer: A

QUESTION 4

An administrator is configuring a SAN-only cluster. The data room that houses four AFF A220 controllers is small and not able to house the DS224C shelves. The administrator proposes to rack the shelves in a separate room that is 40 meters away from the controllers.

In this situation, how would you properly connect the controllers to the shelves?

A. Use multimode passive optical cables.

B. Use multimode active copper cables.

C. Use multimode active optical cables.

D. Use multimode passive copper cables.

Correct Answer: C

Reference: https://library.netapp.com/ecm/ecm_download_file/ECMLP2485106 (45)

QUESTION 5

Click the Exhibit button.

```
Question | Exhibit

AFF::> ucadmin show

                      Current      Current      Pending      Pending       Admin
Node         Adapter  Mode         Type         Mode         Type          Status
----------   -------  ----------   ----------   ----------   ----------    --------
AFF_1        0e       cna          target       -            -             online
AFF_1        0f       cna          target       -            -             online
AFF_1        0g       cna          target       -            -             online
AFF_1        0h       cna          target       -            -             online
AFF_1        1a       fc           target       -            -             online
AFF_1        1b       fc           target       -            -             online
AFF_2        0e       fc           target       -            -             online
AFF_2        0f       fc           target       -            -             online
AFF_2        0g       fc           target       -            -             online
AFF_2        0h       fc           target       -            -
10 entries were displayed.
```

A customer needs to change ports 0e and 0f on AFF_1 to support FC.

Referring to the exhibit, which three steps are required to accomplish this task? (Choose three.)

A. Issue the ucadmin modify -node AFF_1 -adapter 0e -mode FC -type target command.

B. Issue the ucadmin modify -node AFF_1 -adapter 0e -mode FC -type initiator command.

C. Restart the FC service.

D. Take ports 0e and 0f offline.

E. Reboot the node.

Correct Answer: BCD