HP2-K34^{Q&As}

Supporting and Servicing HP 3PAR StoreServ Solutions

Pass HP HP2-K34 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/HP2-K34.html

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

QUESTION 1

What is an accurate description of a CPG and its features?

A. A CPG is a policy that helps you select free chunklets from physical disks within the HP 3PAR StoreServ array. Both full and thin provisioned volumes can be drawn from the same CPG.

B. A CPG is a method of creating a disk pool from which hosts are allocated space; the optimum number of drives in a CPG is 56

C. A CPG is pool-based, and space is reserved upfront for each CPG created The CPG will grow as needed according to its predefined growth increment

D. A CPG is a template that groups the characteristics of a volume, suchas disk media type, disk speed,RAID level, and availability level. A CPG can contain two types of disk media.

Correct Answer: D

QUESTION 2

Which HP resource allows ServiceOne partners to retrieve a customer\\'s existing 3PAR configurations for support and upgrade purposes?

A. HP Proposal Web

B. HPSPOCK

C. HP Professional Service Partner (PSP)

D. HP STaTs

Correct Answer: B

Reference:http://h20272.www2.hp.com/

QUESTION 3

Which statement is correct about using the Guided Maintenance (GM) scripts on an HP 3PAR StoreServ system?

A. The GM scripts have to be run on a 3PARsvc to replace the drive chassis midplane.

B. The Service Processor and node clock battery cannot be removed and replaced by using the GM scripts.

C. The GM scripts have to be run on a 3PARsvc to replace the Service Processor.

D. The Controller Node and drive cage cannot be removed and replaced by using the GM scripts.

Correct Answer: D

QUESTION 4

What is the correct drive configuration to install on an HP 3PAR F200 in a minimal configuration?

A.

B.

C.

D.

A. B. C. D.

A. Option A

B. Option B

C. Option C

D. Option D

Correct Answer: A

Reference:http://h18000.www1.hp.com/products/quickspecs/13884_div/13884_div.PDF(page 14, see magazine population)

QUESTION 5

Which statement is true regarding controller node ports on an HP 3PAR system?

A. iSCSI ports are always set to target mode,

B. Initiator ports receive all the commands from hosts.

C. Remote Copy over IP (RCIP) port is set to peer mode.

D. A target port sends all the commands to the disks.

Correct Answer: C

QUESTION 6

As part of an HP 3PAR implementation, your customer wants all of the servers connected to the SAN to utilize multiple redundant SAN fabrics. However, some of these servers cannot utilize either native or software MPIO. Which HP 3PAR feature should you highlight to this customer?

A. Peer Persistence

B. Peer Motion

C. SecurePath

D. Persistent Ports

Correct Answer: A

QUESTION 7

What is significant about controller slots 1, 4, 2, and 3 on an HP 3PAR 10400?

A. The slots are RCIP, Management, and Console serial slots.

B. The slots are not accessible and are reserved for future use.

C. The slots are recommended for Remote Copy FC.

D. The slots are for disk chassis FC.

Correct Answer: A

QUESTION 8

Your customer is concerned about downtime during the servicing of their HP 3PAR V-Class system. When discussing your action plan with the customer, which resilience factor should you highlight?

A. All data volumes in a V-Class system are configured as HA Cage by default and all enclosures

can be serviced online using this configuration setting

B. All components in an HP 3PAR V-Class system are online serviceable and hot pluggable; there is no need to plan any service downtime

C. When using a second V-Class storage system in the environment, all data access can be switches to the second system during service using the HP Peer Motion technology

D. Power supplies, Fibre Channel Adapters, and drive magazines are all serviceable online without host disruption

Correct Answer: B

Reference:http://www.ts.avnet.com/uk/vendors/hp/assets/hp_p10000_3par_architecture_white_pa per.pdf(page 10, see the last para on the page)

QUESTION 9

What should you discuss during the customer briefing when you perform installs during the winter months?

A. The temperature of the operating environment may be below the minimum safe operating temperature for the storage server.

B. Input AC voltages may be higher than in summer when utilities drop voltages during peak periods

C. The storage server should be brought into the operating environment at least 24 hours prior to installation.

D. Lower humidity leads to an increased need for the anti-static kit.

Correct Answer: AC

QUESTION 10

A storage consultant is explaining the features and functions of Host Explorer to a customer. Which statements are true? (Select two.)

A. HP 3PAR Host Explorer is an agentless Windows, Linux, and Solaris application.

B. HP 3PAR Host Explorer is an application that runs on a host connected to an InServ Storage Server.

C. The Host Explorer communicates with the storage server through a 1Gbit LAN connection.

D. The information gathered from the Host Explorer assists with diagnosing host connectivity issues,

E. The Host Explorer license is part of the VMware Application Suite or can be licensed as a separate product.

Correct Answer: BD

QUESTION 11

Which functionality is enabled when the Secure Network Mode is used?

A. control of outbound communication access via WBEM

B. control of inbound communication access via SMI-S

C. control of inbound/outbound communication access via HTTPS

D. control of inbound/outbound communication access via SSH session

Correct Answer: B

QUESTION 12

A customer has an HP 3PAR 10400, which consists of a controller rack and one disk rack The customer orders an additional disk rack to upgrade the system. What needs to be considered when installing the additional disk rack into the datacenter?

A. The additional disk rack cannot be more than 100 meters from the controller rack

B. Installation of the additional disk rack requires a service outage to the array

C. The additional disk rack requires support of four controllers at a minimum

D. The additional disk rack must be installed on the right hand side of the controller rack.

Correct Answer: B

Latest HP2-K34 Dumps   **HP2-K34 Practice Test**   **HP2-K34 Braindumps**

To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product !

100% Guaranteed Success
100% Money Back Guarantee
365 Days Free Update
Instant Download After Purchase
24x7 Customer Support
Average 99.9% Success Rate
More than 800,000 Satisfied Customers Worldwide
Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications.
You can view Vendor list of All Certification Exams offered:

https://www.passapply.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you.
To update a previously submitted ticket:

Any charges made through this site will appear as Global Simulators Limited.
All trademarks are the property of their respective owners.
Copyright © passapply, All Rights Reserved.