



300-625^{Q&As}

Implementing Cisco Storage Area Networking (DCSAN)

Pass Cisco 300-625 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/300-625.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





QUESTION 1

Refer to the exhibit.

Switch 1

```
Ivr nat
ivr vsan-topology auto
ivr service-group name GROUP1
autonomous-fabric-id 100 vsan-ranges 1-3, 100
autonomous-fabric-id 1 switch 20:00:00:05:31:11:32:ac vsan-ranges 1
autonomous-fabric-id 1 switch 20:00:00:05:40:12:1e:dd vsan-ranges 1-3
```

Switch 2

```
ivr vsan-topology auto
ivr service-group name GROUP2
autonomous-fabric-id 100 vsan-ranges 1, 6-7, 200
autonomous-fabric-id 1 switch 20:00:00:05:31:11:32:ac vsan-ranges 1
autonomous-fabric-id 1 switch 20:00:00:05:40:12:1e:dd vsan-ranges 6-7
```

What is the result of merging the fabric?

- A. The merged fabric IVR VSAN topology is set to activate.
- B. The merged fabric has NAT enabled.
- C. The merge is invalid.
- D. The merged fabric contains only service group Group1.

Correct Answer: D

QUESTION 2

A storage engineer is troubleshooting a Cisco MDS switch upgrade issue. What prevents the completion of a non-disruptive upgrade?

- A. The Fibre Channel host initiator is connected.
- B. The Fibre Channel storage target is connected.
- C. The Cisco Fabric Services operation is in progress.
- D. The Fibre Channel and FCoE storage targets are connected.

Correct Answer: B

Reference: https://www.cisco.com/en/US/docs/storage/san_switches/mds9000/sw/rel_3_x/release/notes/14116.16.html



QUESTION 3

What is the effect of a non-graceful virtual machine shutdown on a virtualized server that is connected to a SAN with Fibre Channel interfaces?

- A. NP Port reload connected to the upstream SAN switch
- B. out-of-service Fibre Channel interfaces on the SAN switch
- C. frames stuck in the storage system
- D. frames stuck in the HBA buffer of the server

Correct Answer: B

QUESTION 4

A storage administrator is connecting two previously configured switches to make a single fabric. When the E Ports are connected, the administrator sees a ZONE MERGE FAILURE message referring to the zoneset for VSAN 10 on each switch. Which command should the administrator use to allow these switches to work together?

- A. zoneset import interface fc1/1 vsan 10
- B. zoneset distribute full vsan 10
- C. zoneset overwrite-control vsan 10
- D. zoneset copy active-zoneset full-zoneset

Correct Answer: A

QUESTION 5

After a subordinate switch requests a domain ID from a principal switch, the requested domain ID becomes the runtime domain ID, and all interfaces on the affected VSAN are isolated. What is a solution to the issue?

- A. Add the received ID to the allowed list.
- B. Configure a static domain on the subordinate switch and reboot the switch.
- C. Enable the FICON feature on the affected VSAN.
- D. Configure IVR NAT on the affected VSAN.

Correct Answer: A