

7303^{Q&As}

Avaya CallPilot Implementation Exam

Pass Avaya 7303 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.passapply.com/7303.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Avaya
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



VCE & PDF PassApply.com

https://www.passapply.com/7303.html

2024 Latest passapply 7303 PDF and VCE dumps Download

QUESTION 1

During the installation of an Avaya CallPilo	ot server that is equipped with RAID	, the following message is received:
"Adaptor 1 Logical Drive 1 is DEGRADLD"	' Which two reasons would cause th	e event to occur? (Choose two.)

- A. Only a portion of the driveis used.
- B. The drive was manuallytakenoff line.
- C. The drive has failed.
- D. Thedrive is no longer using smarttechnology.

Correct Answer: BC

QUESTION 2

The Avaya CallPilot 600r server has one MPM96 card. The PBX it is connecting to will require MGate cards. How many MGate cards are needed to support 80 voice channels?

- A. 1
- B. 2
- C. 3
- D. 4

Correct Answer: C

QUESTION 3

A customer site has a Communication Server (CS) 1000 system and a newly installed Avaya CallPilot RIs. 5.0 on a 600r server. A technician is tasked with installing the Avaya CallPilot Reporter application. Avaya CallPilot Reporter is installed as an option when which Avaya CallPilot web application is installed?

- A. My CallPilot
- B. Avaya CallPilot Manager
- C. Avaya CallPilot Application Builder
- D. Avaya CallPilot UnifiedMessaging

Correct Answer: B

QUESTION 4

A technician observes the following error on a 1006r.



https://www.passapply.com/7303.html

2024 Latest passapply 7303 PDF and VCE dumps Download

"Adapter 1 Channel 1 Target 6: Status of Power Supply #2=0x80: Unknown status, or Status Not Reportable"

Which action should be performed?

- A. Reseat and/or replace Power Supply #2.
- B. Contact an electrician to investigate.
- C. Ensure the alarm monitor cable is properly connected.
- D. The error is self-correcting and no actionis required.

Correct Answer: A

QUESTION 5

Which two additional software packages are installed during the Avaya CallPilot Reporter installation?

- A. Adobo Acrobat
- B. Crystal Repots
- C. Application Builder
- D. a Sybase database

Correct Answer: BD

7303 VCE Dumps

7303 Study Guide

7303 Exam Questions