

HP2-T23^{Q&As}

Supporting Industry Standard Server Solutions

Pass HP HP2-T23 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.passapply.com/hp2-t23.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.passapply.com/hp2-t23.html 2024 Latest passapply HP2-T23 PDF and VCE dumps Download

QUESTION 1

What are features of the HP ProLiant MicroServer? (Select two.)

- A. Sound level of at least 85 DBa
- B. SATA 3.5 inch LFF drives
- C. SAS 2.5 inch SC hot-plug drives
- D. AMD processor
- E. Intel processor
- F. Fibre Channel drives

Correct Answer: BD

QUESTION 2

What are some general requirements that must be met to update Virtual Connect firmware? (Select three.)

- A. The VC domains must not be in Maintenance Mode, so the firmware updates have direct access.
- B. The correct deployment order must be set.
- C. Multiple instances of the Virtual Connect Support Utility (VCSU) must be run, with multiple clients, to access an enclosure faster.
- D. The enclosure must not be part of a domain.
- E. The VC firmware must not be flashed before the configuration is backed up.

Correct Answer: BDE

QUESTION 3

Which step must be performed after the system board is replaced on a ProLiant BL460c G8 server blade?

- A. Enable ASR.
- B. Re-enter the serial number.
- C. Clear the NVRAM.
- D. Reconfigure the array.

Correct Answer: B

https://www.passapply.com/hp2-t23.html

2024 Latest passapply HP2-T23 PDF and VCE dumps Download

QUESTION 4

You cannot get to the network from any of the server blades in a c7000 enclosure with 10GbE Pass-Thru modules.

What should you verify first for proper connectivity to the network?

- A. Correct SFPs are installed
- B. External switch supports at least Gigabit speed
- C. Interconnect link between the Pass-Thru modules
- D. External switch set to half duplex

Correct Answer: C

QUESTION 5

What is a result of selecting the Allow Non-Bundled Versions in HP SUM?

- A. Other non-bundled products can be added to the bundle.
- B. All available firmware will be overwritten.
- C. All products will be updated, including other manufacturers\\' firmware, and updates will be installed with the bundle.
- D. Old and new firmware files can be added and be installed with the bundle.

Correct Answer: D

HP2-T23 PDF Dumps

HP2-T23 Study Guide

HP2-T23 Exam Questions