



# H31-311<sup>Q&As</sup>

HCIA-Transmission V2.5

## Pass Huawei H31-311 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/h31-311.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by Huawei  
Official Exam Center

- ⚙ **Instant Download** After Purchase
- ⚙ **100% Money Back** Guarantee
- ⚙ **365 Days** Free Update
- ⚙ **800,000+** Satisfied Customers





#### QUESTION 1

If a network port that supports auto-negotiation is connected to a network port that does not support auto-negotiation, the half-duplex and full-duplex modes may be interconnected.

- A. TRUE
- B. FALSE

Correct Answer: A

---

#### QUESTION 2

The Erbium Doped Fiber Amplifier (EDFA) is a key component of the new-generation optical communication system. Which of the following are the features of the EDFA? (Multiple Choice)

- A. High gain
- B. High output power
- C. Amplification of any wavelengths
- D. Low noise index

Correct Answer: ABD

---

#### QUESTION 3

Which of the following clock working modes support the ITU-T G.781 standard? (Multiple Choice)

- A. Tracing
- B. Holdover
- C. Free-run
- D. Master/Slave

Correct Answer: ABC

---

#### QUESTION 4

Which of the following bytes in the regenerator section overhead are associated with R-OOF and R-LOF? (Multiple Choice)

- A. A1
- B. A2



C. B1

D. B2

Correct Answer: AB

---

#### QUESTION 5

In the 2.5G MSP ring consisting of four MSTP sites, when a protection switching occurs, which of the following statements about the alarm reporting is correct?

- A. The PS alarm is reported on the tributary board.
- B. The APS-INDI alarm is reported on the XCS board.
- C. The APS-INDI alarm is reported on the system control board.
- D. The APS-INDI alarm is reported on the line board.

Correct Answer: B

[H31-311 PDF Dumps](#)

[H31-311 Study Guide](#)

[H31-311 Braindumps](#)