

HPE0-S60^{Q&As}

Delta - HPE Compute Solutions

Pass HP HPE0-S60 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.passapply.com/hpe0-s60.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.passapply.com/hpe0-s60.html 2024 Latest passapply HPE0-S60 PDF and VCE dumps Download


QUESTION 1

HOTSPOT

An HPE Synergy customer needs to prevent a timeout and loss of communication during an external switch firmware upgrade.


Click the parameter that the customer should configure within an uplink set to meet this requirement.

Hot Area:



Correct Answer:

https://www.passapply.com/hpe0-s60.html 2024 Latest passapply HPE0-S60 PDF and VCE dumps Download



QUESTION 2

DRAG DROP

Your customer plans to use HPE OneView for VMware vCenter Server to deploy ESXi systems. They created a server profile template that they want to use in HPE OneView.

Put the steps required to configure HPE OneView for VMware vCenter Server on the left into their correct order on the right.

Select and Place:



Correct Answer:



2024 Latest passapply HPE0-S60 PDF and VCE dumps Download

Steps		Answer Area
		Add vCenter Server to HPE OneView for VMware vCenter Server.
		Add HPE OneView credentials to the vCenter Server and create OS Deployment Plan.
	_	Upload HPE-friendly ESXi image.
		Deploy new ESXI systems using vCenter Server interface.

QUESTION 3

HOTSPOT

Your customer is implementing an HPE Synergy solution based on three frames.

Click each of the ports that can be used to connect satellite modules.

Hot Area:



Correct Answer:



QUESTION 4


DRAG DROP

After HPE Superdome Flex deployment and nPar setup, you need to verify health status of HPE Superdome Flex components.

2024 Latest passapply HPE0-S60 PDF and VCE dumps Download


Put the steps on the left into the coned order on the right to perform this task.

Select and Place:





Correct Answer:



1	Open SSH client.
2	Open session to RMC.
3	Enter show health command.
4	Confirm health status.


QUESTION 5

HOTSPOT

Click the area within the iLO management interface that will allow you to access workload Advisor.


Hot Area:

2024 Latest passapply HPE0-S60 PDF and VCE dumps Download



Correct Answer:

2024 Latest passapply HPE0-S60 PDF and VCE dumps Download



HPE0-S60 PDF Dumps

HPE0-S60 Practice Test HPE0-S60 Exam Questions