



ISS-003^{Q&As}

Intel Server Specialist Certification Exam

Pass CompTIA ISS-003 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/iss-003.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by CompTIA
Official Exam Center

- ⚙ **Instant Download** After Purchase
- ⚙ **100% Money Back** Guarantee
- ⚙ **365 Days** Free Update
- ⚙ **800,000+** Satisfied Customers





QUESTION 1

A customer configuration based on the Intel Server System R2224WTTYS has an HBA and Fibre Channel adapters installed and ESRT2 enabled. The problem being reported is that the system hangs on boot. Which of the following could be used to resolve the problem? (Select ALL that apply).

- A. The system must have more than 32GB RAM
- B. The HBA may only be used in the second riser slot
- C. Unused OpROMs should be disabled in the BIOS configuration
- D. MMIO should be set to 512GB
- E. ESRT2 must be the first boot device
- F. Enable EFI optimized boot in the BIOS

Correct Answer: CF

QUESTION 2

Your customer has spent a long time on trying to understand what the Cloud is and how it might benefit their business. You have been asked to help in this process. You advise that a good place to start is using the Intel Cloud . Please select the correct answer below.

- A. Creator Services.
- B. Era Builder Services.
- C. Builder Services.
- D. Finder Services.

Correct Answer: D

QUESTION 3

As the Intel® Server Specialist you have an urgent customer call (their customer is still on the phone to them!) complaining that the new server installation is "not working properly!" The Intel® RAID controller RS25PB080 is installed in the Intel® Server System R2208WT2YS. As you complete your troubleshooting "discovery" with your customer, you find that the Intel® RAID Controller is installed in Riser slot 2 and that the controller is not visible either in BIOS or in the OS. How should you advise your customer to proceed?

- A. Ensure that a second CPU is installed
- B. Ensure that the additional six pin power connector is correctly installed
- C. This is a PCIe gen3 device and must be configured accordingly
- D. The RAID activation key should be installed



E. The RAID device should be enabled in BIOS

F. Upgrade to the latest BIOS

Correct Answer: A

QUESTION 4

Which of the following is the device that provides the cache when using SSD cache with Fastpath Premium Feature Key?

A. A writable DVD-ROM

B. RAID controller memory

C. Systemmemory

D. Solid state disks

Correct Answer: D

QUESTION 5

Which of the following are possible ways to find out why a newly integrated Intel Server System is not powering up? (Select ALL that apply).

A. Motherboard diagnostic LEDs

B. System ID LEDs

C. Active system console

D. System Status LED

E. Beepcodes

F. SEL log

G. BIOS error log

Correct Answer: ADE

[ISS-003 PDF Dumps](#)

[ISS-003 Practice Test](#)

[ISS-003 Exam Questions](#)