



SK0-004^{Q&As}

CompTIA Server+ Certification Exam

Pass CompTIA SK0-004 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/sk0-004.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by CompTIA
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

A technician needs to add a processor to a server. Which of the following specifications should the technician examine? (Select THREE).

- A. Bus multiplier
- B. Processor speed
- C. Socket type
- D. Processor stepping
- E. L3 cache size
- F. Thermal specifications

Correct Answer: BCD

QUESTION 2

Which of the following can occur if the maximum rated load is exceeded on an uninterruptible power supply (UPS)?

- A. There is a fire hazard potential if a power outage occurs.
- B. The last system plugged into the UPS will not be provided any power.
- C. The UPS will draw more power from the circuit to compensate.
- D. The runtime of the UPS will be insufficient if a power outage occurs.

Correct Answer: D

QUESTION 3

A system administrator has a database server that crashes at random times. No changes have been made to either the server's software or hardware. Which of the following is the FIRST step the administrator should take towards resolving this issue?

- A. Establish an action plan.
- B. Perform a root cause analysis.
- C. Document the findings.
- D. Identify the problem and scope.

Correct Answer: D

**QUESTION 4**

A server technician needs to connect two servers with gigabit NICs without MDI-X in order to transfer files between them and is unable to locate a switch with gigabit ports. Which of the following types of cables would allow the technician to connect the servers to obtain the FASTEST transfer rate possible?

- A. Rollover cables
- B. CAT6 crossover cables
- C. CAT6 straight-through cables
- D. CAT5 straight-through cables

Correct Answer: B

QUESTION 5

A technician receives errors that a server's internal temperature is approaching an unsafe limit. After opening up the chassis, all fans are operational. Which of the following should be checked NEXT ?

- A. Blockage of the cooling system
- B. Fire suppression system
- C. Uninterruptible power supply load
- D. Location of the server

Correct Answer: A

[SK0-004 PDF Dumps](#)

[SK0-004 Practice Test](#)

[SK0-004 Study Guide](#)