



# HP0-S35<sup>Q&As</sup>

Implementing HP BladeSystem Solutions

**Pass HP HP0-S35 Exam with 100% Guarantee**

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/HP0-S35.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





### QUESTION 1

During the initial set of an HP ProLiant Gen8 server using Agentless Management, where should you configure the SNMP Alert Destination?

- A. System Management Homepage
- B. RBSU
- C. iLO interface
- D. System Insight Manager

Correct Answer: C

---

### QUESTION 2

The customer wants to use a software RAID for the internal disk of the BL860c i2. What must be done?

- A. Use saupdate to set the Controller to HBA mode
- B. Use saconfig to set the Controller to HBA mode
- C. Use ORCA to configure two individual disks
- D. Use drvcfg to configure two individual disks

Correct Answer: A

[http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?lang=en&cc=us&objectID=c02292331&jumpid=reg\\_R1002\\_USEN](http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?lang=en&cc=us&objectID=c02292331&jumpid=reg_R1002_USEN)



```
16.93.73.165 - PuTTY
fs2:\> saupdate set_mode all hba -f

Changing mode of the controller at 0:2:0:0 to HBA
Resetting and reinitializing controller,it may take several minutes
Controller mode change successful

Changing mode of the controller at 0:42:0:0 to HBA
Resetting and reinitializing controller,it may take several minutes
Controller mode change successful

Changing mode of the controller at 0:82:0:0 to HBA
Resetting and reinitializing controller,it may take several minutes
Controller mode change successful

Changing mode of the controller at 0:C2:0:0 to HBA
Resetting and reinitializing controller,it may take several minutes
Controller mode change successful

fs2:\> █
```



```
16.93.73.165 - PuTTY
fs2:\> saupdate set_mode 0:2:0:0 hba
WARNING:Changing controller mode could result in DATA LOSS!!!
Key in 'YES' to continue or 'NO' to quit:yes
The controller at 0:2:0:0 is already in HBA mode
fs2:\> saupdate set_mode 0:2:0:0 raid
WARNING:Changing controller mode could result in DATA LOSS!!!
Key in 'YES' to continue or 'NO' to quit:no
No mode change done
fs2:\> saupdate set_mode 0:2:0:0 raid
WARNING:Changing controller mode could result in DATA LOSS!!!
Key in 'YES' to continue or 'NO' to quit:yes
Changing mode of the controller at 0:2:0:0 to RAID
Resetting and reinitializing controller,it may take several minutes
Controller mode change successful
fs2:\> saupdate set_mode p410i raid
WARNING:Changing controller mode could result in DATA LOSS!!!
Key in 'YES' to continue or 'NO' to quit:yes
The controller at 0:2:0:0 is already in RAID mode
Changing mode of the controller at 0:42:0:0 to RAID
Resetting and reinitializing controller,it may take several minutes
Controller mode change successful
Changing mode of the controller at 0:82:0:0 to RAID
Resetting and reinitializing controller,it may take several minutes
Controller mode change successful
Changing mode of the controller at 0:C2:0:0 to RAID
Resetting and reinitializing controller,it may take several minutes
Controller mode change successful
```

### QUESTION 3

You set up an HP Integrity i2 blade running HP-UX for HP Insight Remote Support and want to test the solution. Which tool do you use to generate a test event?

- A. System Management Homepage
- B. System Fault Management
- C. WEBEM Provider
- D. Event Monitoring System



Correct Answer: C

4. Click Add Protocol, enter the name of the protocol and select the type as UNIX WBEM. Click Add New Protocol.

#### QUESTION 4

Which view should you select to create a baseline or baseline group in VMware Vcenter Update manager version 4.1?

- A. Customization
- B. Management
- C. Admin
- D. Compliance

Correct Answer: C

[http://www.vmware.com/pdf/vsp\\_vum\\_41\\_admin\\_guide.pdf](http://www.vmware.com/pdf/vsp_vum_41_admin_guide.pdf) Pages 14-15

### Update Manager Client Overview

The Update Manager Client has two main views, Administration view and Compliance view.

To access the Administration view, you can use the **Update Manager** icon under Solutions and Applications in the vSphere Client Home page or click **Admin view** from the **Update Manager** tab. In the Update Manager Client Administration view, you can do the following tasks:

- Configure the Update Manager settings
- Create and manage baselines and baseline groups
- View Update Manager events
- Review the patch repository
- Add or remove patches or extensions from a baseline
- Review and check notifications
- Import host upgrade releases

To view Compliance view information for a selected inventory object, click the **Update Manager** tab in the Hosts and Clusters or VMs and Templates inventory view of the vSphere Client. In the Update Manager Client Compliance view, you can do the following tasks:

- View compliance and scan results for each selected inventory object
- Attach and detach baselines and baseline groups from a selected inventory object
- Scan a selected inventory object
- Stage patches or extensions to hosts
- Remediate a selected inventory object

#### QUESTION 5



What is different about the Intel processors in HP ProLiant G7 and Gen8 server?

- A. support for 512-bits processing
- B. support for 3.3 V processor module
- C. processor module socket type
- D. support for 1024-bits processing

Correct Answer: C

---

#### QUESTION 6

A customer needs many HP BladeSystem servers equipped with additional server option Which HP service should be recommended?

- A. Factory Express
- B. Optimized Care
- C. Configure to Order
- D. Rapid Deployment

Correct Answer: C

---

#### QUESTION 7

An administrator has just installed the latest service pack for Microsoft Windows Server 2008 R2. What else needs to be done to keep the server up to date?

- A. Uninstall Microsoft patches
- B. Delete the temporary install files
- C. Remove older security updates
- D. Re-install the ProLiant Support Pack or HP Service Pack for ProLiant

Correct Answer: D

---

#### QUESTION 8

What is the minimum number of CPU sockets that must be populated in a BL890c i2?

- A. 1
- B. 2
- C. 4



D. 6

Correct Answer: C

Reference: [http://h18004.www1.hp.com/products/quickspecs/13619\\_na/13619\\_na.HTML](http://h18004.www1.hp.com/products/quickspecs/13619_na/13619_na.HTML) (Step 2:Choose Required Options; hp processors, see the note)

Upgradeable to eight (8) processors

NOTE: The HP Integrity BL890c i2 supports 4, 5, 6, 7, or 8 processor configurations. Processors must be identical.

---

#### QUESTION 9

Which Onboard Administrator feature ensures that the management processor in a server bay always has the same IP address?

- A. Static Management Processor for the bay
- B. IP Bay Addressing (IPBA)
- C. DHCP MAC Filtering
- D. Enclosure Bay IP Addressing (EBIPA)

Correct Answer: D

---

#### QUESTION 10

Which statement is correct about using an ESD strap when replacing a memory DIMM?

- A. It prevents exposure to a potentially lethal amount of current
- B. It prevents electro-static discharge that could potentially damage electronics
- C. It prevents exposure to a lethal amount of voltage
- D. It is not needed because ESD cannot be felt.
- E. It is no longer needed since ESD protection is built into the equipment

Correct Answer: B

---

#### QUESTION 11

An HP Blc 4x QDR InfiniBand switch is intalled in Bays 3 and 4 in a c7000 enclosure. What is the maximum number of downlink ports that it provides for connections to blade server?

- A. 8
- B. 16



C. 32

D. 64

Correct Answer: B

[http://h18004.www1.hp.com/products/quickspecs/12586\\_div/12586\\_div.PDF](http://h18004.www1.hp.com/products/quickspecs/12586_div/12586_div.PDF)

HP BLc 4X QDR IB Switch for HP BladeSystem c-Class Double wide switch blade for the new c7000 enclosure with 16 downlink ports to connect server blades via the midplane. and 16 QSFP unlink ports for the inter- switch links or to connect to external servers. All ports are capable of supporting 40Gbps (QDR) bandwidth. All uplink ports support copper and fiber optic cables. The switch is externally managed, i.e. a subnet manager has to be provided on the fabric (see the subnet manager discussion above)

---

#### QUESTION 12

What are troubleshooting areas for a FC EVA array?

A. Server smart array

B. FC zoning

C. IFM on the SAN switch

Correct Answer: B

[HP0-S35 PDF Dumps](#)

[HP0-S35 VCE Dumps](#)

[HP0-S35 Study Guide](#)





To Read the [Whole Q&As](#), please purchase the [Complete Version](#) from [Our website](#).

## Try our product !

100% Guaranteed Success  
100% Money Back Guarantee  
365 Days Free Update  
Instant Download After Purchase  
24x7 Customer Support  
Average 99.9% Success Rate  
More than 800,000 Satisfied Customers Worldwide  
Multi-Platform capabilities - [Windows](#), [Mac](#), [Android](#), [iPhone](#), [iPod](#), [iPad](#), [Kindle](#)

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

<https://www.passapply.com/allproducts>

## Need Help

Please provide as much detail as possible so we can best assist you.  
To update a previously submitted ticket:



 <p><b>One Year Free Update</b> Free update is available within One Year after your purchase. After One Year, you will get 50% discounts for updating. And we are proud to boast a 24/7 efficient Customer Support system via Email.</p>	 <p><b>Money Back Guarantee</b> To ensure that you are spending on quality products, we provide 100% money back guarantee for 30 days from the date of purchase.</p>	 <p><b>Security &amp; Privacy</b> We respect customer privacy. We use McAfee's security service to provide you with utmost security for your personal information &amp; peace of mind.</p>
---	---	--

Any charges made through this site will appear as Global Simulators Limited.  
All trademarks are the property of their respective owners.  
Copyright © passapply, All Rights Reserved.