

# 200-401<sup>Q&As</sup>

Managing Industrial Networks with Cisco Networking Technologies (IMINS)

# Pass Cisco 200-401 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/200-401.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



## https://www.passapply.com/200-401.html

2024 Latest passapply 200-401 PDF and VCE dumps Download

#### **QUESTION 1**

What are the two most relevant factors in determining the class of administration that is required to maintain the telecommunications infrastructure? (Choose two.)

- A. the size of the infrastructure
- B. the complexity of the infrastructure
- C. the age of the infrastructure
- D. the industry that the infrastructure supports
- E. the physical environment of the infrastructure

Correct Answer: AB

#### **QUESTION 2**

In which two ways could you minimize the impact of monitoring an industrial network? (Choose two.)

- A. Send random messages to a device and see what the response is.
- B. Do frequent ping sweeps to industrial devices to check for their proper operations.
- C. Make a copy of all the network traffic and analyze it offline.
- D. Use an industrial-network-grade IDS-IPS system.

Correct Answer: CD

## **QUESTION 3**

The network administrator is using a Windows PC application that is called putty.exe for remote communication to a switch for network troubleshooting. Which two protocols could be used during this communication? (Choose two).

- A. SNMP
- B. HTTP
- C. Telnet
- D. RMON
- E. SSH

Correct Answer: CE

#### **QUESTION 4**



## https://www.passapply.com/200-401.html 2024 Latest passapply 200-401 PDF and VCE dumps Download

With what are APC connectors used?

- A. Category 6a cables that need tight radius bends
- B. copper network cables in corrosive environments
- C. single-mode fiber-optic cables to reduce return loss
- D. high-density copper patch panels

Correct Answer: C

#### **QUESTION 5**

Which three pieces of information must be maintained for all stakeholders as part of the change management process? (Choose three.)

- A. the location of the person who applied the change
- B. the date and time that the change was applied and on which device
- C. the original change request form that indicates why the change is necessary
- D. the size of the change (in bytes)
- E. a description of the actual change itself (configuration, program code, and so on)
- F. the names of the current members of the change advisory board
- G. the industrial protocol that is used

Correct Answer: BCE

200-401 VCE Dumps

200-401 Practice Test

200-401 Braindumps