



500-920^{Q&As}

Cisco Data Center Unified Computing Infrastructure Troubleshooting
(DCITUC)

Pass Cisco 500-920 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/500-920.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

Which two interfaces allow access to Cisco UCS Manager? (Choose two)

- A. Cisco KVM
- B. Cisco UCS Manager XML API
- C. Cisco IMC
- D. Cisco UCS Manager GUI

Correct Answer: BD

QUESTION 2

What is the likely cause of an intermittent SAN Boot fails?

- A. Misconfigured SAN boot target in the boot policy of the service profile
- B. LUN ID Mismatch
- C. FCoE used instead of FC
- D. Wrong boot order in the service profile

Correct Answer: A

QUESTION 3

Which statement best describes managing Cisco UCS servers using NX-OS CLI on the Fabric Interconnects?

- A. The NX-OS CLI on the Fabric Interconnects allows you to view, but not change the connectivity configuration between the Fabric Interconnects and an upstream LAN switch.
- B. The NX-OS CLI on the Fabric Interconnects allows you to manage QoS parameters on the Fabric Interconnects and an upstream LAN switch
- C. The NX-OS CLI on the Fabric Interconnects allows you to change the connectivity configuration between the servers and Fabric Interconnects
- D. The NX-OS CLI on the Fabric Interconnects allows you to change the connectivity configuration between the Fabric Interconnects and an upstream LAN switch.

Correct Answer: D

QUESTION 4

When troubleshooting a LAN connectivity issue, you notice a failed uplink from the Cisco UCS Fabric Interconnects to



the upstream LAN switch. What two could be causing the issue? (Choose two)

- A. Misconfigured VLAN on the failed uplink
- B. Misconfigured QoS parameters on the failed uplink
- C. A port channel mismatch between the Fabric Interconnects and the upstream LAN switch
- D. A SFP Type mismatch between the Fabric Interconnects and the upstream LAN switch
- E. A port speed configuration mismatch between the Fabric Interconnects and the upstream LAN switch

Correct Answer: BC

QUESTION 5

You are experiencing intermittent connectivity issues on one specific Cisco UCS server. Some applications work, while others do not transfer data. You suspect jumbo frame limitations.

Which two places do you check the jumbo frame settings? (Choose two)

- A. Check server's service profile and/or service profile template
- B. Check server's QoS System Class
- C. Check the fibre channel port configuration for jumbo frame configuration
- D. Check upstream switch ports frame size configuration
- E. Check server's individual vNICs and/or vHBAs properties

Correct Answer: BD

[Latest 500-920 Dumps](#)

[500-920 PDF Dumps](#)

[500-920 Study Guide](#)