

# 642-980<sup>Q&As</sup>

Troubleshooting Cisco Data Center Unified Fabric

### Pass Cisco 642-980 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.passapply.com/642-980.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Cisco
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



### https://www.passapply.com/642-980.html

2021 Latest passapply 642-980 PDF and VCE dumps Download

#### **QUESTION 1**

FCoE appears to be properly configured. Which two steps should you take to verify the FCoE configuration? (Choose two.)

- A. Run the feature fcoe command.
- B. Verify that the jumbo MTU is properly set.
- C. Ensure that the license has been applied.
- D. Utilize the proper CoS values on each side.

Correct Answer: BD

#### **QUESTION 2**

Storage VDC creation has failed. Which two steps should be taken before creating the storage VDC? (Choose two.)

- A. Check that the F1 module has the FCoE license installed.
- B. Check that the FCoE feature is enabled on the N7K.
- C. Check that you have allocated the interfaces of the F module on the VDC.
- D. Check that the network QoS non-drop policy is configured for FCoE traffic.
- E. Check that the FCoE VLANs are allocated on the VDC.
- F. Check that the M2 module has the FCoE license installed.

Correct Answer: BD

#### **QUESTION 3**

There is an ARP storm in VDC 1. Some users on VDC 2 notice that ARP is not resolving for their gateway on the Cisco Nexus core. What is the cause?

- A. The ARP CoPP class committed information rate is exceeded, resulting in ARP loss in all VDCs.
- B. The administrator has not correctly configured the ARP CoPP class in VDC 2.
- C. The ARP traffic in VDC 1 is copied to the host ports in VDC 2, causing overutilization and output discards.
- D. Because the ARP process in the default VDC (VDC 1) is responsible for processing ARP traffic for all VDCs, VDC 2 will be affected.

Correct Answer: A

### https://www.passapply.com/642-980.html

2021 Latest passapply 642-980 PDF and VCE dumps Download

#### **QUESTION 4**

#### Instruction




- Enter NX-OS commands on the device to verify network operation and answer the multiple-choice questions.
- THIS TASK DOES NOT REQUIRE DEVICE CONFIGURATION.
- · Click on the Console PC to gain access to the console of the router. No console or enable passwords are required.
- · To access the multiple-choice questions, click on the numbered boxes on the left of the top panel.
- There are three multiple-choice questions with this task. Be sure to answer all three questions before clicking the Next button.

#### Scenario



The following three troubleshooting questions concern the Cisco Nexus 7000 and Nexus 5000 switches, which are at the core of the data center network. You can utilize all the available **show** commands to answer the questions. Access to the running configuration is not allowed.









The Cisco Nexus 2248 FEX has been added recently to the network via a vPC to the Nexus 5000 switches; however, connectivity is not yet operational. What is the problem with the configuration?



### https://www.passapply.com/642-980.html

2021 Latest passapply 642-980 PDF and VCE dumps Download

- A. Both Nexus 5000 switches must associate to the same FEX number
- B. Each Nexus 5000 should have its own FEX to support a straight-through topology.
- C. The maximum number of links for pinning purposes should be increased to 2.
- D. Ethernet1/18 must be configured without a port channel.

Correct Answer: D

#### **QUESTION 5**

Refer to the exhibit.

No of sessions: 1 (Max: 32) 🔊

Total number of commands (Max: 102400)

Session Database Lock Info: Locked

Client: 2 (1: SSN, 2: CONF-T) Ref count: zero-based ref-count

Lock acquired for cmd: some-command

What is the cause of the ISSU failure when using the command show system internal csm globalinfo?

- A. The command conf-t is holding a lock and not released it.
- B. The SSN feature is not enabled on both switches.
- C. The reference count is less than 1 due to a lack of successful config-sync.
- D. It cannot be determined from the output.
- E. An Administrator is logged in on another session and has a lock of the session data base to prevent ISSU.

Correct Answer: A

642-980 PDF Dumps

642-980 Practice Test

642-980 Study Guide



To Read the Whole Q&As, please purchase the Complete Version from Our website.

## Try our product!

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

**Instant Download After Purchase** 

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.passapply.com/allproducts

### **Need Help**

Please provide as much detail as possible so we can best assist you. To update a previously submitted ticket:





Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © passapply, All Rights Reserved.