

9L0-008^{Q&As}

Macintosh Service Certification Exam

Pass Apple 9L0-008 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.passapply.com/9L0-008.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Apple
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



VCE & PDF PassApply.com

https://www.passapply.com/9L0-008.html

2021 Latest passapply 9L0-008 PDF and VCE dumps Download

QUESTION 1

Which THREE of the following a	are valid CRT saf	fety rules? SELECT	THREE
--------------------------------	-------------------	--------------------	-------

- A. Touch the computer\\'s metal chassis.
- B. Wear a grounded ESD wrist strap.
- C. Connect the AC power cord.
- D. Remove any metal jewelry.
- E. Wear safety goggles.
- F. Don\\'t work alone.

Correct Answer: DEF

QUESTION 2

You are troubleshooting an eMac that has no image on its built-in display. You have already checked user controls and reset PRAM, but the issue persists. When you connect an external display to the eMac\\'s VGA output port and restart the eMac, you see a proper image on the external display. Which of the following service modules would most likely be the cause of these symptoms?

- A. Display Analog Assembly
- B. Power Supply Assembly
- C. Logic Board
- D. Hard drive

Correct Answer: A

QUESTION 3

You are attempting to power a Mac mini (original) with an 85 Watt power adapter. Will this work?

- A. Yes
- B. No

Correct Answer: A

QUESTION 4


A. Can you open any files?

- B. Can you open other Keynote files?
- C. Is your Mac connected to a network?
- D. What version of Keynote are you using?

Correct Answer: B

QUESTION 5

Examine the exhibit. Which of these is a valid memory configuration for a Mac Pro (Early 2008)?



A. Configuration A: Two DIMMs on top riser card, four DIMMs on bottom riser card.

B. Configuration B: Four DIMMs on top riser card, two DIMMs on bottom riser card.

Correct Answer: B

9L0-008 Practice Test

9L0-008 Exam Questions

9L0-008 Braindumps



To Read the Whole Q&As, please purchase the Complete Version from Our website.

Try our product!

100% Guaranteed Success

100% Money Back Guarantee

365 Days Free Update

Instant Download After Purchase

24x7 Customer Support

Average 99.9% Success Rate

More than 800,000 Satisfied Customers Worldwide

Multi-Platform capabilities - Windows, Mac, Android, iPhone, iPod, iPad, Kindle

We provide exam PDF and VCE of Cisco, Microsoft, IBM, CompTIA, Oracle and other IT Certifications. You can view Vendor list of All Certification Exams offered:

https://www.passapply.com/allproducts

Need Help

Please provide as much detail as possible so we can best assist you. To update a previously submitted ticket:





Any charges made through this site will appear as Global Simulators Limited.

All trademarks are the property of their respective owners.

Copyright © passapply, All Rights Reserved.