

9L0-012^{Q&As}

Mac Service Certification Exam

Pass Apple 9L0-012 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.passapply.com/9I0-012.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Apple
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers





https://www.passapply.com/9I0-012.html 2024 Latest passapply 9L0-012 PDF and VCE dumps Download

QUESTION 1

Which component for Apple Service Toolkit is designed to help troubleshoot issues with MagSafe and MagSafe 2 power adapters?

^	NIAD
Α.	NAD

B. VST

C. TPT

D. CSD

Correct Answer: A

Explanation:

Apple Service Toolkit includes:*

AudioTest — plays a series of tones through each speaker and listens for those same tones via the microphone.

Diagnostic Gateway (DG) — software that runs on a dedicated Intel-based Mac using Mac OS X Server 10.6/10.7 and serves up tools to triage computers via NetBoot, recording test results as log files.

Mac Resource Inspector (MRI) — triage tool that provides a fast check of internal hardware

components for all Intel-based computer systems.

Notebook Adapter Diagnostic (NAD) — triage tool that reports on the condition of Intel-based notebook power adapters.

Cooling System Diagnostic (CSD) – evaluates the thermal sensors, fans and heat sink in MacBook Pro (Early 2011) models and will either confirm correct operation or help diagnose a service issue.

Gateway Manager — software application used to remotely configure and manage the Diagnostic Gateway server as well as access logs created by diagnostic tools.

Test Patterns Tool (TPT) – identifies pixel anomalies in LCD panels in Apple Display, iMac, MacBook, MacBook Pro, and MacBook Air systems.

Server Bit Setter (SBS) – Repair tool used after replacing logic boards in late model Mac mini Servers or backplane boards in late model Mac Pro Servers.

Video System Test (VST) – is used to test video issues in specific MacBook Pro models.

Blank Board Serializer (BBS) – Allows technicians to set the system serial number on replacement Main Logic Board (MLB) service parts.

AST Keyboard (OS) – service tool for in-depth testing of keyboards.

AST Trackpad (OS) – service tool for in-depth testing of trackpads.

Storage Diagnostic (OS) – Repair tool for testing HDD or SSD modules.

Image Persistence Test (EFI) – triage tool for identifying image persistence anomalies on IPS displays



https://www.passapply.com/9I0-012.html 2024 Latest passapply 9L0-012 PDF and VCE dumps Download

QUESTION 2

If the glass panel on an iMac or Thunderbolt Display is broken and still attached to the rear housing, with what will you secure the broken display?

- A. Glue
- B. Very High Bond (VHB) adhesive
- C. Packing tape
- D. Thermal compound
- E. Painters tape

Correct Answer: C

Reference: http://mdex-nn.ru/uploads/imac12.pdf (page 11)

QUESTION 3

Which of the following is NOT a good step to take when working on-site on a computer\\'?

- A. Place parts on the floor.
- B. Use a grounded ESD mat
- C. Wear a grounded ESD wrist strap.
- D. Check the polarity of the grounded power outlet.

Correct Answer: A

QUESTION 4

When conducting an internal inspection of MacBook Air (13-inch, Mid 2011) for accidental damage, why is it necessary to remove the battery?

- A. There are liquid contact indicators on the underside of the battery module.
- B. The battery is always removed in every repair on this unit.
- C. The battery covers all of the spill sensors on the top case.
- D. The battery must be removed to install the battery cover.

Correct Answer: A

Reference: http://www.mybigcampus.com/bundles/unit-5-accidental-damage-and-macbook-air--- 276227



https://www.passapply.com/9I0-012.html 2024 Latest passapply 9L0-012 PDF and VCE dumps Download

QUESTION 5

What is the likely cause of an iMac (21.5-inch, Late 2013) producing a single error tone at startup that repeats every five seconds.

- A. The unit does not have RAM or RAM is not installed properly.
- B. The logic board has failed and must be replaced.
- C. The RAM does not pass data integrity tests.
- D. The hard drive has failed S.M.A.R.T. status.

Correct Answer: A

Reference: https://support.apple.com/en-ca/HT202768

<u>Latest 9L0-012 Dumps</u> <u>9L0-012 Practice Test</u> <u>9L0-012 Braindumps</u>