



# CQE<sup>Q&As</sup>

Quality Engineer Exam

## Pass ASQ CQE Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/cqe.html>

100% Passing Guarantee  
100% Money Back Assurance

Following Questions and Answers are all new published by ASQ Official Exam Center

-  **Instant Download** After Purchase
-  **100% Money Back** Guarantee
-  **365 Days** Free Update
-  **800,000+** Satisfied Customers





#### QUESTION 1

If a distribution is skewed to the right

- A. The mode is between the median and the mean.
- B. The mean is between the mode and the median.
- C. The mode is greater than the median.
- D. None of the above.

Correct Answer: D

---

#### QUESTION 2

Measurement gaging is preferable to go, no-go gaging of a quality characteristic because

- A. It is more scientific.
- B. It provides the most information per piece inspected.
- C. It requires greater skills.
- D. It requires a larger sample than go, no-go gaging does.

Correct Answer: B

---

#### QUESTION 3

The probability of an accident for the head event "H" given below is:

- A. 0.0700
- B. 0.1125
- C. 0.0689
- D. 0.1100

Correct Answer: C

---

#### QUESTION 4

According to Tchebysheff's theorem what % of measurements must lie within 2.5 standard deviations of the mean?

- A. 3/4
- B. 8/9



C. 0.840

D. 0.625

Correct Answer: C

---

#### QUESTION 5

Failure mode, effect, and criticality analysis, (FMECA) is primarily for the purpose of

A. Learning as much about the item as possible after qualification test.

B. Determining the way an item will most likely fail to help obtain design and procedural safeguards against such failures.

C. Determining, by extensive analysis, the reliability of an item.

D. Determining the cause of a failure, by dissecting the item, to help obtain corrective action.

Correct Answer: B

[CQE VCE Dumps](#)

[CQE Practice Test](#)

[CQE Brainsdumps](#)