



CWDP-303^{Q&As}

Certified Wireless Design Professional

Pass CWNP CWDP-303 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/cwdp-303.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by CWNP
Official Exam Center

- ⚙ **Instant Download** After Purchase
- ⚙ **100% Money Back** Guarantee
- ⚙ **365 Days** Free Update
- ⚙ **800,000+** Satisfied Customers





QUESTION 1

Which document provided to your customer should include all devices and parts that are going to be used during the deployment of their WLAN infrastructure?

- A. SoW
- B. BoM
- C. Design report
- D. Project plan

Correct Answer: B

Reference: <https://searcherp.techtarget.com/definition/bill-of-materials-BoM>

QUESTION 2

Your customer requires fast secure roaming. Which two types of roaming are specified in 802.11-2016 FT roaming that will help meet this goal?

- A. Over-the-Air and Over-the-DS
- B. Over-the-Air and Over-the-Wire
- C. FT and OKC
- D. FT and TKIP

Correct Answer: A

QUESTION 3

After deploying a 5 GHz-only WLAN infrastructure in the USA, using 20 MHz channel-widths and all 25 available channels, one of the managers of the company brings his 802.11n tablet to the office to test the Guest SSID. While testing, there were several spots where we would get poor RSSI (below -80dBm) or none at all. You checked the WLAN infrastructure and all APs are up and running and you've validated coverage after deployment. What is causing this issue?

- A. His tablet doesn't support the 5 GHz band
- B. His tablet only supports a 40 MHz channel-width
- C. His tablet does not support one or more of the 5 GHz channels
- D. His tablet doesn't support MU-MIMO

Correct Answer: D

**QUESTION 4**

What is the most cost-effective way to accurately measure the height of a ceiling when ladder use is not allowed?

- A. Estimate the height based on known object sizes
- B. Gather measurements from other objects and do the math
- C. Rent a lift-cart to lift you up to the ceiling
- D. Use a laser measure to measure the distance from the floor to the ceiling

Correct Answer: D

QUESTION 5

When deploying a new WLAN infrastructure using PoE to power the APs, you realize that a known good AP is not powering up. You use the same cable to connect your laptop and connect without any trouble. What is the most likely reason the AP did not power up?

- A. Missing AP licenses in the controller
- B. Spanning-tree convergence
- C. Layer 3 routing
- D. Lack of PoE budget on the switch

Correct Answer: D

[CWDP-303 PDF Dumps](#)

[CWDP-303 Exam Questions](#)

[CWDP-303 Braindumps](#)