

H31-341^{Q&As}

HCIP-Transmission V2.5

Pass Huawei H31-341 Exam with 100% Guarantee

Free Download Real Questions & Answers PDF and VCE file from:

https://www.passapply.com/h31-341.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Huawei
Official Exam Center

- Instant Download After Purchase
- 100% Money Back Guarantee
- 365 Days Free Update
- 800,000+ Satisfied Customers



https://www.passapply.com/h31-341.html

2024 Latest passapply H31-341 PDF and VCE dumps Download

QUESTION 1

Which of the following is not a precaution after board replacement?

- A. Record the settings of jumpers and DIP switches on the board.
- B. /For functional units that have backups, check whether the switchover is normal.
- C. Check the indicator blinking status of the board and ensure that the board works properly.
- D. Ensure that no abnormal alarm.

Correct Answer: D

QUESTION 2

Which of the following statements about the modulation technologies of the 40Gbit/s and 100Gbit/s coherent systems are correct?

- A. The modulation technology used in a 100G coherent system is ePDM-QPSK.
- B. The modulation technology used in a 40G coherent system is ePDM-BPSK.
- C. The modulation technology used in a 40G coherent system is ePDM-QPSK.
- D. The modulation technology used in a 100G coherent system is ePDM-BPSK.

Correct Answer: A

QUESTION 3

Which of the following statements about the Service Package is incorrect?

- A. You can configure service packages in two modes. One is to configure boards in batches, and the other is to configure each board.
- B. Service package enables one-click configuration of typical services by issuing multiple configuration commands in batches, facilitating product deployment commissioning and reducing maintenance costs.
- C. The Service Package can configure the working mode, service type, cross-connection, and port type in batches.
- D. Currently, Service Package is available to the TOA, TOX and TSC boards.

Correct Answer: C

QUESTION 4

Before querying bit errors and optical power on the U2000, you need to perform the () operation. Otherwise, the corresponding data cannot be queried.



https://www.passapply.com/h31-341.html

2024 Latest passapply H31-341 PDF and VCE dumps Download

- A. Enabling the NE Performance Monitoring Time
- B. Creating the logical fiber
- C. Synchronizing NE data
- D. Configuring data

Correct Answer: D

QUESTION 5

FXS and FXO are the names of the ports used by analog telephone lines. FXO ports and FXS ports are always used in pairs.

A. True

B. False

Correct Answer: A

H31-341 PDF Dumps

H31-341 Study Guide

H31-341 Braindumps