



HPE0-S58^{Q&As}

Implementing HPE Composable Infrastructure Solutions

Pass HP HPE0-S58 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

<https://www.passapply.com/hpe0-s58.html>

100% Passing Guarantee
100% Money Back Assurance

Following Questions and Answers are all new published by HP Official Exam Center

- ⚙️ **Instant Download** After Purchase
- ⚙️ **100% Money Back** Guarantee
- ⚙️ **365 Days** Free Update
- ⚙️ **800,000+** Satisfied Customers





QUESTION 1

DRAG DROP

Match each HPE server platform with optimal workload.

Select and Place:

Platform	Workload
Apollo	<input type="text"/> in-memory databases and financial risk management
ML server	<input type="text"/> Object Storage/Big Data
Simplivity	<input type="text"/> single applications supporting 15 users
SuperDome Flex	<input type="text"/> Virtual Desktop infrastructure with GPU support

Correct Answer:

Platform	Workload
<input type="text"/> SuperDome Flex	in-memory databases and financial risk management
<input type="text"/> Apollo	Object Storage/Big Data
<input type="text"/> Simplivity	single applications supporting 15 users
<input type="text"/> ML server	Virtual Desktop infrastructure with GPU support

QUESTION 2

A customer needs to expand a single-frame Synergy solution to two frames.

What should the integrator do to establish a proper management network for the two frames?

- A. Connect the RJ-45 management ports of the Virtual Connect modules together with redundant CAT6A cables.
- B. Disconnect the existing management ring, and cable the Frame Link Modules in the first frame to the Frame Link



Modules in the added frame.

C. Connect the RJ-45 front panel connectors on the two frames together with a single CAT6A cable.

D. In the Synergy console, select the Frame Link Modules in the new frame and define the connection between them.

Correct Answer: D

QUESTION 3

A customer needs to deploy additional management components, such as vCenter Server and HPE Global Dashboard. According to HPE best practices, how should an integrator deploy these components?

A. Deploy VMware HA cluster on two dedicated management servers, then deploy management components to this cluster.

B. Deploy vCenter Server as a virtual machine on the Hyper-V host and HPE Global Dashboard to the domain controller.

C. Install vCenter Server on the domain controller, then deploy HPE Global Dashboard to the HPE Composer or HPE OneView appliance.

D. Deploy vCenter Server to any Windows machine, and install HPE Global Dashboard on the same server.

Correct Answer: B

QUESTION 4

A customer tries to revert a data volume located on the HPE 3PAR array to a specific snapshot that was taken using HPE Composer, but the process fails. What must an integrator do to fix this problem?

A. Install the snapshot agent on the operating system to enable online snapshot operations

B. Select the "Force" checkbox to ignore the warning, and revert to the snapshot because this is a data volume

C. Navigate to the SSMC and revert to the snapshot using HPE 3PAR tools

D. Disconnect the volume from the server, then revert to the snapshot and reconnect back to the server

Correct Answer: C

QUESTION 5

During a first-time installation of HPE Synergy, an external monitor is not available to the integrator. Which approach should the integrator take to perform the first-time setup?

A. Download MSTCS, connect the laptop to the front Panel Ethernet port, and open a RDP Session to 192.168.10.1 on port 443.

B. Download VNC Viewer, connect the laptop to the front Panel Ethernet port, and open a VNC-connection to 192.168.10.1 on port 5900.



C. Download Telnet, connect the laptop to the front Panel Ethernet port, and open a connection to 192.168.10.1 on port 8443.

D. Download PuTTY, connect the laptop to the front Panel Ethernet port, and open an SSH connection to 192.168.10.1 on any port (default is 22).

Correct Answer: B

[Latest HPE0-S58 Dumps](#)

[HPE0-S58 PDF Dumps](#)

[HPE0-S58 Practice Test](#)