

7003.1^{Q&As}

Avaya Communication Server 1000 for Avaya Aura Implementation Exam

Pass Avaya 7003.1 Exam with 100% Guarantee

Free Download Real Questions & Answers **PDF** and **VCE** file from:

https://www.passapply.com/7003-1.html

100% Passing Guarantee 100% Money Back Assurance

Following Questions and Answers are all new published by Avaya Official Exam Center

Instant Download After Purchase

- 100% Money Back Guarantee
- 😳 365 Days Free Update
- 800,000+ Satisfied Customers





QUESTION 1

A customer with a Communications Server (CS) RIs. 6.0 HA system with two IPMGs and dual CPPM signaling Servers is upgrading their system to release 7x with Avaya Aura integration with Session Manager. The system is part of an IP peer network that includes a NRS database that needs to be converted and imported into the System Managre.

Which upgrade setup is correct?

A. Use NRS manager to download the NRS backup file to compact flash and upload the nrs.xml file into system manager for automatic database conversion

B. Use Element Manager to download the Signaling Server backup file to a compact flash and upload the nrs.xml file to CS 100 NRS data Conversion Tool to convert so it can be imported into Session Manager

C. Use NRS manager to download the NRS backup file to the local PC and upload the nrs.xml file to the 1000 NRS data Conversion Tool to convert so it canbe imported into System Manager

D. Use Element Manager to download the Signaling Server backup file to the local PC and convert the nrs.xml file using the data conversion Tool in the utilities folderin the Linux Base compact flash

Correct Answer: C

QUESTION 2

A customer wants to build a new Ip node on their Communication Server (CS) 1000E system with three Signaling Servers. This node will support virtual trunks, IP media services, TPS and personnel directories. A technician logs into Elements manager to complete the configuration, after creating and saving the node configuration, the transfer now option chosen, then the servers are selected, the start sync is selected followed by restart application.

What is expected outcome from the system?

A. The node file will be transferred from Signaling Servers to the call servers, and INI files will be transferred from the call server to the selected servers.

B. The node file will be transferred from Call Servers to the Signaling servers, and the INI files will be transferred from the Call Servers to the selected servers.

C. The node file will be transferred from Signaling Servers to the Call Server, and the INI files will be transferred from Call Servers to the Signaling servers.

D. The node will be transferred from Element manager to the call server, and INI files will be transferred from Element manager to CallServer.

Correct Answer: B

QUESTION 3

A technician on a Communication Server 1000E SA RIs. 7x cannot get a second media Gateway to register with the Call Server. The call server and Media Gateway 1 sit in the same 19 inch rack while Media Gateway 2 is in another building and connected via the computer IP network Media Gateway 2 can ping the Call Server but cannot register. The network is suspected of having a firewall or port blocking issue. Which diagnostic tool will help to isolate and identify a



firewall or port blocking issue between the call server and Media Gateway 2?

- A. Gryphon Tool
- B. Packet Capture Tool
- C. Linux PPP Tool
- D. Linux Modem Configuration Tool

Correct Answer: B

QUESTION 4

A technician is planning an upgrade for a customer\\'s Communication Server (CS) 1000E Release 6.0 system to Release 7x.

Which two features are now to the Release 7x Deployment manager? (Choose two)

- A. Pre-configuration Remote Installation
- B. Auto-select servers to which applications can be deployed
- C. One-Touch System Upgrade
- D. Auto-Select of the correct application file

Correct Answer: AC

QUESTION 5

Click the Exhibit button. A customer has added a new Communication Server 1000E (CS 1000E) Standard Availability to their existing network of CS 1000M Single Group system. They are planning to use some of the spare digital telephone on the new system as well as new IP telephone. With reference to system showing three vacant slots, which two components are required to configure the system so that the digital telephone are supported and can communicate with the IP telephone? (Choose two)

- A. TMDI Card
- B. IP Line Card
- C. Digital Line Card
- D. CPPM Signaling Server

Correct Answer: CD

QUESTION 6

A customer has deployed a Communication Server 100 Rls. 7x system at their site. The technician has been asked to add the Call pickup feature to the 100 IP telephone in the sales department. The customer wants to be sure active calls



not lost when the changes are made.

Which Phones Configuration feature can be enabled that will ensure changes to the telephone are not transmitted to the call server until the telephone are busy?

- A. Bulk change
- B. Courtesy change
- C. Group change
- D. Template change

Correct Answer: B

QUESTION 7

From which two ports is the Fully Qualified Domain Name (FQDN) composed, and in what order must they be configured?

- A. First the host name and then the domain name
- B. First the domain name and then the host name
- C. First the COTS server IP address and then the port number
- D. First the COTS server port number and then the IP address

Correct Answer: A

QUESTION 8

A customer with an existing Option 11C Rls. 5.5 chassis system plans to upgrade to a Communication Server (CS) 1000E Rls. 7x Standard Availability with a single IP Media Gateway (MG) 1000E chassis.

To complete the upgrade, which component in the Option 11C must be replaced?

- A. SSC Card
- **B. Call Processor**
- C. Media Gateway
- D. Digital Line Card

Correct Answer: A

QUESTION 9

Click the Exhibit Button.



Features Special prefix number: Network authorization code: Internal/external definition: | Analog semi-permanent connection re-connection (10 - 180)timer Network station camp-on to sets on this node: List entry number delimiter No delimiter(*) Mandatory speed call delimiter. [Personal call assistant OFF Target personal call assistant DN: Boss secretary filtering enhancement Lamp status when bess's set has BSFE active and LCD Lamp flash rate is 60 impulses perimited Lamp status when boss's set has BSFE active and LCD Lamp flash rate is 30 impulses per Lamp status when boss's set does not have BSFE LCO Lamp is off active and is idle. Lamp status when boss's set doesn't have BSEE (Enable virtual office automatic logout Virtual office automatic logout time using 24 hour clock Change conference display contigurations IP Enable conference count display field: 17 Change conferees count display field name: CONF Enable internal conferees count display field: 🔽 Change internal conferees count display field. I Enable total external conferees count display field Change total external conferees count field name. E Enable numbering zone:

A customer has asked if the Communication Server (CS) 1000 Rls. 7x system can provide Executive users with the ability to selectively drop people that have been added to a conference.

Based on the print-outs and assuming the CSD key has been programmed and the class of service assigned is CDCA, which capabilities are currently available to the user of extension 2006?

- A. The user cannot see the conferee display count or selectively disconnect callers.
- B. The user can see the conferee display count and can selectively disconnect callers.
- C. The user can see the conferee display count but cannot selectively disconnect callers.
- D. The user cannot see the conferee display count but can selectively disconnect callers



Correct Answer: B

QUESTION 10

A customer has completed the installation of the Communication Server (CS) 1000E Rls. 7 x system and wants to access Base Manager to configure and provision the Linux Base.

Which two actions are true regarding access Base manager? (Choose two)

- A. Base Manager is accessible from the UCM element list
- B. Base Manager is accessible from Deployment Manager
- C. Base Manager is accessible via centralized login for standalone Linux servers
- D. Base Manager is accessible on every server with Linux Base in or out of a security domain

Correct Answer: AC

QUESTION 11

Click the Exhibit button.

	Contraction of the local division of	a second s	0	and the second se	Pint Batreat
Linux Server Add	Delete	Deployment Actions 💌		View: Servers	
Host Name *		Deployment Actions Backup	Status	Predeployed Applications	Base V
cs1k02a ks1n lab avaya com/primary	Restore	Predeployed	CS, EM, SS, NRS, SubM	7.00.19	
				and the second	-
FS status' enabled Disable					Commit
		applications, and need to be	a configured into	systems	

A technician is performing an upgrade of existing Communication Server 1000E RIs. 6.0 servers from the Deployment Servers. The system is pre-configured and the status is un-deployed. The server has been selected, but the Deployment Actions pull-down list does not include the choice to deploy.

Which two corrective actions must be taken to continue with deployment? (Choose two)

- A. Click the radio button associated with the server
- B. Click the Disable NFS button
- C. Click the Commit button
- D. Click the add Linux Server button

Correct Answer: A



QUESTION 12

You are installing a new Communication Server 1000E HA Release 7x system for your customer. Which two lists can be created using the lists feature provided with the EM phones Tool? (Choose two)

- A. Speed Call Lists
- B. Dial Intercom Lists
- C. Call Pickup Lists
- D. Group Call Lists

Correct Answer: AD

QUESTION 13

Click the exhibit button During the installation the installation of a Communication Server 1000E RIs. 7x High Availability system for a customer, attempts to register an IP 1230 Desktop telephone with the system are unsuccessful. Network connectivity issues have already been ruled out, however a system configuration issue is suspected.



100 malaunu analiantian	DIDO	Virtual Trank Network Health Monitor
Vtrk gateway application:		
SIP domain name:	voice.servicedomain.com	C Monitor IP addresses (listed below)
Local SIP port	5060 *(1 - 05535)	Information will be captured for the IP addresses list below
		Monitor IP
Gateway endpoint name:	cs1k01a ·	1000
Gateway password:		Monitor addresses:
	-	
H.323 ID:	cs1k01a ·	Famore
Application node ID:	*(0-9999)	
Enable failsafe NRS	F	
SIP ANAT		
OR ALLAL	And the second	
the second s	C IFV6 m Line Terminal Proxy Service	
the second s	m Line Terminal Proxy	
UNISEM Line Terminal Proxy S	m Line Terminal Proxy : Server. 🏳 Enable proxy service (
UNISSIM Line Terminal Proxy S Firmware	m Line Terminal Proxy : Server. ["Enable proxy service	
UNISEm Line Terminal Proxy S Firmware IP address: 0.0.0	m Line Terminal Proxy : Server. ["Enable proxy service	
UNISEm Line Terminal Proxy S Firmware IP address: 0.0.0 Full file path: down Server Account/User ID.	m Line Terminal Proxy : Server. ["Enable proxy service	
UNISSim Line Terminal Prox S Firmware IP address: 0.0.0 Full file path: down	m Line Terminal Proxy : Server. ["Enable proxy service	
UNISEm Line Terminal Proxy S Firmware IP address: 0.0.0 Full file path: down Server Account/User ID.	m Line Terminal Proxy : Server. ["Enable proxy service	
UNISEm Line Terminal Prox S Firmware IP address 0.0.0 Full file path dow Server Account/User ID Password	m Line Terminal Proxy : Server. ["Enable proxy service	
UNISSim Line Terminal Proxy S Firmware IP address: 0.0.0 Full file path: down Server Account/User ID. Password:	m Line Terminal Proxy : Server. ["Enable proxy service : 10 nio adlfirmwai	
UNISEm Line Terminal Proxy S Firmware IP address: 0.0.0 Full file path: gow Server Account/User ID Password: DTLS policy. Off	m Line Terminal Proxy : Server. ["Enable proxy service of 10 nio additirmival	

What is causing the problem?

- A. The virtual gateway application is not enabled.
- B. The proper firmware has not been uploaded for this telephone.
- C. The Line Terminal Proxy Server is not enabled for the node
- D. The Datagram Transport Layer Security (DTLS) Policy off.

Correct Answer: C

QUESTION 14

A customer is commissioning a Communication Server (CS) 1000E 7x system with package 403 (soft switch) and 402



(IPMG). The CPDC Call Server software has been installed successfully, and now the customer is provisioning the Media Gateway Tone and conference loops for the Media Gateway Controller.

Which switch overlay and prompt should the customer use to configure the Media gateway TDS loop?

A. LD 17, XCT

B. LD 17, VXCT

C. LD 17, SUPT

D. LD 17, MGTDS

Correct Answer: A

QUESTION 15

A technician is installing a new Communication Server (CS) 1000E Rls. 7x system for a customer. The requirements include installation of IP telephones for a small group of inside sales people. The telephones have been configured and are ready to be registered.

Which two items are to be entered when performing the IP telephone registration? (Choose two)

A. The Directory Number

B. The Node ID

- C. The Terminal Number
- D. The Customer Number

Correct Answer: BC

Latest 7003.1 Dumps

7003.1 VCE Dumps

7003.1 Study Guide